

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SLR 4448D

Vehicle Model : KIA CERATO K3 SUNROOF

Accident Date : 02.08.2020

Original Reg Date : 16.08.2017

Date : 11.08.2020

Chassis : KNAFZ411MH5720550

TP Ins. CHINA

ESTIMATE

1	1 pc	Front Bumper	920	? de ✓	710
2	1 pc	Front Bumper Badge	52	de ✓	
3	2 pcs	Front Bumper Side Retainers @ 39 each	78	LH de ✓, RH x nn	39
4	1 set	Front Bumper Clips	40	de ✓	30
5	1 pc	Front Bumper Reinforcement	420	? XR	
6	1 pc	Front Bumper Sponge	172	? de ✓	172
7	1 pc	Front Bumper Lower Grille	164	x nn.	
8	1 pc	Front Bumper Number Plate Base	112	? de ✓	
9	2 pcs	Front Bumper Sensor @ 85 each	370	LH de ✓, RH x nn	185
10	2 pcs	Front Bumper Sensor Holder	70	x nn	
11	1 pc	Front Bumper Fog Lamp RH	356	x nn.	
12	1 pc	Front Grille	478	? de ✓	256
13	1 pc	Front Grille Chrome Moulding	136	? de ✓	
14	1 set	Front Grille Clips	30	de ✓	
15	1 pc	Headlamp LED LH	220	? de ✓	
16	1 pc	Headlamps Bottom Retainers LH	72	? de ✓	

Acknowledged by Repairer
Signature: _____
Date: _____
Less 10%
is subject to approval from Insurance Company
• Supplementary item(s) must be resurveyed and
• No illegal modification(s) is allowed
• Third party survey is on a "Without Prejudice" basis
• Parts prices are subject to confirmation
• To display damaged part(s) during resurvey
• To resurvey before/after spray painting

Special Nett

1	1 pc	Front Bumper Lower Spoiler	1,000.00	XR
2	1 pc	Front Number Plate with Cover	45 70.00	

Labour charge

Panel Beating	300	600.00
Spray painting	400	600.00
Check Wiring	20	30.00
Anti rust	x nn	30.00
Remove and install front sensor.	30	70.00

Tanpin 97495746
- WP 12/8/2020 1115.
• 3 days - 4 days tanpin @ 1 hour per km.
Lump sum
Residing after repair

3602.70
45
750
4397.70
1/5 \$ 3500, 3 days
Less 20%
2,400.00
480.00
1,920.00
7515.60