



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY			Ref: CC4/ASM20008111/Ags3q2 Date: 05/01/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SHD 9475M	Veh. Inspected	SKL 3313J
	Policy No.	VFX/P1680520	Coverage (\$)	0.00
	Claim No.	S0M02RPS	Excess (\$)	0.00
	Assign From		Assign Date	05/08/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA CAMRY	c.c	2487
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MR2B63HK104000413	Colour	BRONZE
	Odometer	57219 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	235/45 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	235/45 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	235/45 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	235/45 R18	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	05/08/2020	Inspection Date	06/08/2020
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	