

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

05/08/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAxA.

Cecilia.

Accident date: 05/08/2020

Estimated repair cost for vehicle no: SKL3313J TOYOTA CAMRY 2.5A 19'

CHASSIS: MR2B63HK104000413

S/n	Qty	Items	U/price	Amount
1	1	Front R/H Headlamp <i>lit</i>		\$2,721.00 ✓
2	2	Front Headlamp Lower Bracket <i>new</i>	\$175.10	\$350.20 +
3	1	Front Grille		\$851.90 +
4	8	Front Grille Clip	\$6.50	\$52.00 +
5	1	Front Grille Chrome		\$371.10 +
6	1	Front Grille Emblem Logo		\$1,673.30 +
7	1	Front Bumper <i>Del</i>		\$581.10 ✓
8	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
9	1	Front R/H Bumper Side Retainer <i>new</i>		\$178.25 ✓
10	1	Front R/H Bumper Fog Lamp		\$371.45 +
11	1	Front R/H Bumper Fog Lamp Cover <i>new</i>		\$381.90 +
12	1	Front Bumper Center Lower Garnish		\$581.45 +
13	1	Front Bumper Sensor (Special Nett) <i>Repl</i>		\$350.00 2w(su)
14	1	Front Bumper Inner Foam <i>can be</i>		\$171.45 ✓
15	1	Front Bumper Reinforcement <i>new</i>		\$581.10 +
16	1	Front R/H Fender <i>Repl</i>		\$731.35 +
17	1	Front R/H Fender Cowling <i>form</i>		\$581.10 249.70
18	8	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 30
19	1	Front Support Panel		\$1,218.00 +
20	1	Front Support Panel Top Cover <i>new</i>		\$581.00 +
21	1	Front Brace Panel		\$172.75 +
22	1	Front R/H Lower Arm <i>Bent</i>		\$378.20 ✓
23	1	Front R/H Knuckle Arm <i>Repl</i>		\$578.10 ✓
24	1	Front R/H Knuckle Arm Bearing <i>new</i>		\$278.10 ✓
25	1	Front R/H Shock Absorber <i>new</i>		\$578.10 +
26	1	Front R/H Rim <i>lit</i>		\$850.00 550(su)
27	1	Front R/H Tyre <i>lit</i>		\$350.00 250(su)
28	1	Front Water Tank <i>repl</i>		\$231.02 ✓

Subtotal :- \$15,860.92

5426.92
4070.15

S.N: 1000

Labour charges

To remove & refit front sensor

\$180.00 ~~60~~

To check wiring

\$100.00 ~~30~~

Tuff kote

\$150.00 ~~30~~

Panel beating

920

\$1,100.00 ~~400~~

Spray painting

\$1,000.00 ~~400~~

Subtotal :- \$2,350.00

Total:- \$18,210.92

Adrian L
L/S 06/08/20

05 Days.

Total 5590.19.
L/S: 4.8K

48K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: