## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Date: 11 Aug 2020

# **Preliminary Advice**

Insured Vehicle No : SLX9865T

TP Vehicle No : SKE9660D Accident Date : 29/07/2020 Make : HONDA 400X Assignment Date : 05/08/2020

Date of Inspection : 07/08/2020 Est. Duration of Repair : 2

Inspection At : AVANTAGE VAG (HQ)

48 TOH GUAN ROAD EAST SINGAPORE 608586

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,199.34
Revised Amount	:S\$	1,691.88
Check Items (Estimated)	:S\$	687.14
Total	:S\$	2,379.02

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$
Pre-Accident Value :S\$
COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

### Remarks

(

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: Survey on WP