

ACRA NUMBER: 200911678H

GST REGISTRATION NUMBER : 200911678H

05 August 2020

Our Ref: FBK 6690L (V) EQUATOR

Your Ref: SHA 3721H

India International Insurance Pte Ltd

64 Cecil Street #04/#05 IOB Building Singapore 049711

**Attn: Motor Claims Department** 

RIAZ QAYYUM ILLB HONSI NUS

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS (ASSOCIATE)

MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS

(ASSOCIATE)

IRFAN NASRULHAQ BIRMÆMAIL ONLYNSI SMU (ASSOCIATE)

## **NOTICE OF ACCIDENT**

Dear Sir

TO:

We are instructed by our client to *notify* you of a road traffic accident on <u>26 JULY 2020</u> at about <u>2100</u> hours along <u>Sembawang Road</u> involving our client's vehicle registration number <u>FBK 6690L</u> and vehicle registration number <u>SHA 3721H</u> driven by you or your authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : EQUATOR BROTHERHOOD

Address : 25 KAKI BUKIT ROAD 4

#03-79 SYNERGY @ KB SINGAPORE 417800

Telephone no. : 6384 6939/9011 3391 (Wille)

Please let us hear from you by the stipulated time.

Yours faithfully

cc Client

**FOR SURVEYOR** 

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor (Name & signature)

Date & time of inspection

