

SIN BOON MOTOR CO

10. ADMIRALTY STREET,
#01-10, NORTHLINK BUILDING,
SINGAPORE 757695.
TEL: 62578404, FAX 67556214

FBQ1418J- ESTIMATED REPAIR BILL
MODEL: YAMAHA TRICITY 155 ABS
YEAR OF MANUFACTURE: 2019 [31-07-2019]

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

5-AUG-2020

Acknowledged by Repairer

Signature:

Date:

1	1 PC	EXHAUST COVER / CR4	\$85.00 /
2	1 PC	RIGHT SIDE UNDER SPOILER / SCR	\$105.00 /
3	1 PC	RIGHT SIDE MUDGUARD - GREY COLOUR / SCR	\$85.00 /
4	1 PC	RIGHT SIDE TOP CLOWING OUTER / SCR	\$85.00 /
5	1 PC	HANDLE BAR / BT	\$105.00 /
6	1 PC	RIGHT SIDE BRAKE LEVER / SCR	\$30.00 /
7	1 PC	RH BALANCER / SCR	\$28.00 /
8	1 PC	WIND SCREEN / SCR	\$95.00 /
			\$618.00 /
LESS 10 %			\$61.80 /
			\$556.20 /
9	1 PC	FRONT NO PLATE / NEC.	\$18.00 /
10	1 PC	RH FRONT RIM BALANCING X Svc.	\$40.00 X
11	1 PC	WIND SCREEN BOX bolt / Nec.	\$15.00 /
12		TOWING / Nec	\$100.00 /
13		LABBOUR CHARGE	\$250.00 / 50
			\$979.20
GST			\$68.54
TOTAL			\$1,047.74

263.

Repair day - 2 days
P/P
before put in photo.

Sun Pin (LHK)
TP without prejudice
05/08/2020.
Sunpin@lkkauto.com



新文摩哆公司
SIN BOON MOTOR CO.
NORTH LINK BUILDING
10 ADMIRALTY STREET #01-10/11
SINGAPORE 757695
TEL: 6257 8404, 6758 3716
FAX: 6755 6214

6

P = 556.2
L = 263
819.2

P/P
\$819.2
2 days