

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008117/QVF3E2

**Date:** 09/09/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00022502000
Claimant Vehicle No :	FBQ1418J	Insured Vehicle No :	SDQ3365R
Date of Loss:	14/06/2020	Nature of Claim:	TP
		Claim No:	SNM20D202137/C02/THAMYL

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ1418J	Engine No:	G3H3E058972
Make & Model:	YAMAHA TRICITY, 155cc ABS	Chassis No:	MLESG381000058972
Reg. Date:	31/07/2019 (Man. Year: 2019)	Odometer:	0 km
Colour:	Grey		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	90/80-14	Rear Tyre Size:	90/80-14
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	629.20	589.20	40.00	6.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	230.00	120.00	34.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>979.20</b>	<b>819.20</b>	<b>160.00</b>	<b>16.34</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>68.54</b>	<b>57.34</b>	<b>11.20</b>	<b>16.34</b>
<b>Nett Amount (S\$)</b>	<b>1,047.74</b>	<b>876.54</b>	<b>171.20</b>	<b>16.34</b>

### INSPECTION

Date of Assignment:	05/08/2020	
Date Inspected:	05/08/2020 Inspected At:	SIN BOON MOTOR CO 10, ADMIRALTY STREET #01-10/11 NORTHLINK BUILDING . SINGAPORE 757695
Estimated Period of Repair:	2.0 days	

**Adjuster:** OI SUN PIN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 09 Sep 2020)	
<b>Parts:</b>	N/A	YAMAHA TRICITY 155cc ABS (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBQ1418J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST COVER	Crumpled	85.00 FL	*85.00 FL
2	1		*RIGHT SIDE UNDER SPOILER	Scratched	105.00 FL	*105.00 FL
3	1		*RIGHT SIDE MUDGUARD - GREY COLOUR	Scratched	85.00 FL	*85.00 FL
4	1		*RIGHT SIDE TOP CLOWING OUTER	Scratched	85.00 FL	*85.00 FL
5	1		*HANDLE BAR	Bent	105.00 FL	*105.00 FL
6	1		*RIGHT SIDE BRAKE LEVER	Scratched	30.00 FL	*30.00 FL
7	1		*RH BALANCER	Scratched	28.00 FL	*28.00 FL
8	1		*WIND SCREEN	Scratched	95.00 FL	*95.00 FL
9	1		*FRONT NO PLATE	Necessary	18.00 FS	*18.00 FS
10	1		*RH FRONT RIM BALANCING	Serviceable	40.00 FS	*- FS
11	1		*WIND SCREEN BOLT	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>691.00</b>	<b>651.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	61.80	61.80
<b>Total Parts (\$\$)</b>	<b>629.20</b>	<b>589.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	100.00	80.00
2	LABOUR CHARGE	New	250.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>350.00</b>	<b>230.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >