

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 40687**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0480/2020/NS  
**Date** : 8-Jul-20

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle no : SLL 9791 K**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Chan Moy Jin  
**Address** : 33 Oxford Road  
#06-13  
Singapore 218816  
**Telephone** : (HP)+65 86119811  
**Type of Claim** : Own Damage Claims  
**Policy No.** : 1700063167-02  
**Vehicle No** : **SLT 235 S**  
**Model Code** : Audi A1 SB 1.0 TFSI S TRONIC  
**Model / Year** : Oct-17  
**Engine No** : CHZ 507976  
**Chassis No** : WAUZZZ8X8JB013259  
**Mileage** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 7-Jul-20  
**Place of Accident** : Along Dorset Rd

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLT 235 S

| S/N                         | Parts Description                          | <u>Damage Parts &amp; Prices</u> |          |
|-----------------------------|--------------------------------------------|----------------------------------|----------|
|                             |                                            | S/Nett                           | Remarks  |
| 1                           | FRONT DOOR - LH <i>Y</i> ✓                 | \$ 1,915.00                      | 1,532.00 |
| 2                           | FRONT DOOR ATTACHMENT PARTS <i>new</i> ✓   | \$ 126.00                        | X        |
| 3                           | FRONT DOOR CATCH X                         | \$ 84.00                         | ✓ 66.88  |
| 4                           | EXTERIOR MIRROR MOUNTING - LH <i>scd</i> ✓ | \$ 434.00                        | 363.60   |
| 5                           | EXTERIOR DOOR HANDLE <i>repair</i>         | \$ 146.00                        |          |
| 6                           | DOOR HANDLE CAP <i>repair</i>              | \$ 28.00                         |          |
| 7                           | REAR DOOR - LH <i>bt</i> ✓                 | \$ 1,915.00                      | 1,607.20 |
| 8                           | REAR DOOR ATTACHMENT PARTS <i>new</i> ✓    | \$ 79.00                         | X        |
| 9                           | REAR DOOR HINGE - LH UPPER ?               | \$ 143.00                        | X        |
| 10                          | REAR DOOR HINGE - LH LOWER ?               | \$ 125.00                        | X        |
| 11                          | REAR DOOR CATCH X                          | \$ 84.00                         |          |
| 12                          | AIRBAG STICKER X                           | \$ 23.00                         |          |
| 13                          | REAR ALUMINIUM RIM - LH <i>scd</i> ✓       | \$ 666.00                        | 532.40   |
| 14                          | STONE CHIP <i>new</i> ✓                    | S/N \$ 180.00                    |          |
| 15                          | SUNDRIES ?                                 | \$ 300.00                        | ✓ 6.88   |
| <b>TOTAL SPARE PARTS</b>    |                                            | <b>: \$ 6,248.00</b>             |          |
| <b>TOTAL LABOUR CHARGES</b> |                                            | <b>: \$ 10,182.00</b>            |          |
| <b>GRAND TOTAL</b>          |                                            | <b>: \$ 16,430.00</b>            |          |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLT 235 S

| S/N                         | Nature of Jobs                                                                                                                                                                                                 | Estimated Charges     | Surveyor Reccomend. |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|---------------------|
| 1                           | To dismantle lhs front door panel trim. To remove and renew lhs wing mirror assy.                                                                                                                              | S/N \$ 350.00         | X                   |
| 2                           | To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.                                                                                     | S/N \$ 560.00         |                     |
| 3                           | To dismantle and renew lhs front door and lhs rear door. To repair lhs sill panel, lhs B-pillar, door entrance and lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed. | \$ 3,500.00           | 1250                |
| 4                           | To respray lhs front door, lhs rear door, lhs B-pillar, lhs sill panel, door handle, door entrance, hinges and lhs rear fender.                                                                                | \$ 5,300.00           | 2300                |
| 5                           | To renew lhs rear rim and carry out wheel alignment.                                                                                                                                                           | S/N \$ 280.00         |                     |
| 6                           | To carry out diagnostic check.                                                                                                                                                                                 | S/N \$ 192.00         |                     |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                                                                | <b>: \$ 10,182.00</b> |                     |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

: Rasul - Hp 9000068

Surveyed Date

: 05/08/2020 @ 1100 hrs

Authorised Date

:

Excess Cost

:

7 days

Liability

:

EXCESS: TPA

Remarks

:

Reay before paint

REPAIR

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant

# Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

## Supplementary Estimate 1

GST Reg No. 19-9902271-W

| <b>AIG Asia Pacific Insurance Pte Ltd</b><br>78 Shenton Way<br>#07-16 AIG Building<br>Singapore 079120<br><b>Attn: Mr. Adrian Ling - Motor Claims Dept</b><br><b>Tel: 6841 0055 - Fax: 6256 4315</b> |                                                    | <b>Estimate No.</b><br><b>Date</b><br><b>Service Advisor</b><br><b>Pages</b><br><b>Regn No</b><br><b>Model No</b> | PA/OD/0480/2020/NS<br>25-Aug-20<br>Glory Tan<br>1 OF 1<br>SLT 235 S<br>Audi A1 SB 1.0 TFSI S TRONIC |  |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|--|
| Quantity                                                                                                                                                                                             | Description                                        | Unit Price                                                                                                        | Amount                                                                                              |  |
| <u>Parts</u><br>1                                                                                                                                                                                    | lhs rear fender stone chip guard foil <b>nec</b> ✓ | \$ 42.00                                                                                                          | 33.44                                                                                               |  |
| <b>TOTAL</b>                                                                                                                                                                                         |                                                    | <b>\$ 42.00</b>                                                                                                   |                                                                                                     |  |

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
Authorised Signature