

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44081

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0537/2020/NS
Date : 4-Aug-20

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Thaw Tint
Address : 16 Balmoral Road
 #07-03
 Siangapore 259802
Telephone : (HP) +65 93200417
Type of Claim : Own Damage Claims
Policy No. : 1700065489
Vehicle No : **SLT 258 B**
Model Code : Audi A5 SB 2.0 TFS
Model / Year : 13/10/2017
Engine No : CVK 047182
Chassis No : WAUZZZF51JA034302
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Aug-20
Place of Accident : Bideford Rd Paragon Carpark Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 258 B

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove & transfer/reinstall front bumper wire harness for front parking aid system.	S/N	\$ 280.00 ✓	
2	To remove and transfer rhs headlight control unit. And power module. To carry out calibration.	S/N	\$ 400.00 250	
3	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.		\$ 2,400.00 1000	
4	To respray front bumper and rhs front fender.		\$ 2,200.00 1100	
5	To renew rhs front rim and carry out wheel alignment.	S/N	\$ 280.00 ✓	
6	To dismantle, inspect and renew rhs front suspension assy.	S/N	\$ 1,800.00 ✓	
7	To carry out diagnostic check.	S/N	\$ 192.00 ✓	
TOTAL LABOUR CHARGES		:	<u>\$ 7,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 258 B

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
		\$	2,251.00	✓
1	FRONT BUMPER Distorted	\$	402.00	✓
2	FRONT BUMPER FIXING PARTS New	\$	70.00	✓
3	FRONT BUMPER SECURING STRIP ?	2 \$	225.00	X
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE New	\$	62.00	X
5	FRONT BUMPER AIR GUIDE - RH 2 New	\$	468.00	X
6	FRONT BUMPER AIR GUIDE GRILLE - RH	\$	36.00	✓
7	FRONT BUMPER GUIDE SECTION - RH Dented	\$	123.00	X
8	FRONT BUMPER FOAM FILLER PIECE New	\$	795.00	?
9	FRONT BUMPER CARRIER ?		TBC	?
10	FRONT PARKING AID SENSOR - FRONT OUTER ?	\$	1,048.00	✓
11	FRONT FENDER - RH Dented	\$	53.00	?
12	FRONT FENDER ATTACHMENT PARTS ?	\$	73.00	?
13	FRONT FENDER CLOSING ELEMENT - RH ?	\$	35.00	?
14	FRONT FENDER BRACKET - RH ?	\$	117.00	✓ S/S
15	FRONT FENDER BRACE - RH Bent.	\$	49.00	?
16	DEFORMATION ELEMENT BRACKET - RH ?	\$	35.00	?
17	FRONT FENDER BRACKET ?	\$	35.00	?
18	TOP FENDER LEDGE COVER - UPPER ?	\$	16.00	?
19	TOP FENDER LEDGE COVER - LOWER ?	\$	157.00	✓
20	FRONT FENDER TRIM - RH New	\$		
SUB TOTAL SPARE PARTS CHARGES		\$	6,050.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 258 B

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/	Nett	
		\$	272.00	✓
21	WHEEL HOUSING LINER - RH <i>deformed</i>	\$	73.00	✓
22	WHEEL SPOILER <i>fan</i>	\$	36.00	?
23	WHEEL SPOILER TRIM - RH ?	\$	50.00	✓
24	STONE CHIP GUARD - RH <i>new</i>	\$	7,812.00	✓
25	LED HEADLIGHT - RH <i>at</i>	\$	196.00	✓
26	LIFT CYLINDER - RH <i>new</i>	\$	1,012.00	✓
27	FRONT ALUMINIUM RIM - RH <i>at</i>	\$	533.00	✓
28	FRONT WISHBONE LINK - RH <i>Best</i>	\$	932.00	✓
29	FRONT SUSPENSION GUIDE - RH <i>Best</i>	\$	506.00	✓
30	FRONT UPPER CONTROL ARM - RH <i>Best</i>	\$	506.00	✓
31	REAR UPPER CONTROL ARM - RH <i>Best</i>	\$	957.00	✓
32	WHEEL BEARING HOUSING - RH <i>Best</i>	\$	191.00	✓
33	SWIVEL JOINT <i>Best</i>	\$	790.00	✓
34	WHEELHUB <i>Best</i>	\$	195.00	✓
35	TIE ROD END - RH <i>Best</i>	\$	300.00	✓
36	SUNDRIES			
TOTAL SPARE PARTS CHARGES		\$	20,411.00	
TOTAL LABOUR CHARGES		\$	7,552.00	
GRAND TOTAL		\$	27,963.00	

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian L.
05/08/20

: Not Authorised, 05 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant