

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 1997G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	2,256.40	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	2,201.10	-
1	FRONT DOOR HANDLE RH	TO REPAIR SEE LABOUR	36.30	-
1	REAR DOOR HINGE RH / UPP	NOT NECESSARY	53.40	-
1	FRONT FENDER RH	BENT	663.00	663.00
	LESS 20% DISCOUNT		-1,042.04	-132.60
			4,168.16	530.40
	<u>SPECIAL NETT ITEMS</u>			
1	FRT DOOR COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	REAR DOOR APP LOGO (SN)	NECESSARY	80.00	80.00
			155.00	155.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH, REAR DOOR RH AND FRONT DOOR HANDLE RH.		540.00	420.00
	SPRAY PAINTING CHARGE.		800.00	700.00
	REMOVE / REFIX DOOR PARTS.	NOT NECESSARY	180.00	-
	TUFF KOTE.		120.00	30.00
	CHECK LIGHTING.	NOT NECESSARY	60.00	-
			1,700.00	1,150.00
	GRAND TOTAL		6,023.16	1,835.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,450.00

Report Ref No. NS/INC20008124/T1vf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.