

## PAIR ESTIMATE\*

VEHICLE NO SHC1997G

MAKE :

MODEL I-40

DATE 05/08/2020  
CHIANG/NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR RH			\$2,256.40
1	REAR DOOR RH			\$2,201.10
1	FRONT DOOR HANDLE RH			\$36.30
1	REAR DOOR HINGE RH/UPP			\$53.40
1	FRONT FENDER RH			\$663.00
	<b>SUB TOTAL</b>			<b>\$5,210.20</b>
	<b>20.00%</b>			<b>\$1,042.04</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$4,168.16</b>
1	FRT DOOR COMFORT LOGO			\$75.00
1	REAR DOOR APP LOGO			\$80.00
				<b>\$155.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$540.00
	Spray Painting Charge			\$800.00
	Remove /Refix door parts			\$180.00
	Tuff Kote			\$120.00
	Check Lighting			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,700.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$6,023.16</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanpin 92495789  
 -up 5/8/20 @ 3pm  
 Lumpsun (2) 03 days  
 Resurvey after repair  
 Tanpin @ lhand.com  
 Han Kook

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1835.40  
 1450  
 2 days  
 #