

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 44082

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0540/2020/NS
Date	:	4-Aug-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Ms Poh Kee Boon
Address	:	51 Hillview avenue #03-03 Singapore 669565
Telephone	:	+(HP) 90011522
Type of Claim	:	Own Damage Claim
Policy No.	:	1800116420
Vehicle No	:	SKQ 33 K
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	Sep-18
Engine No	:	CYR 065575
Chassis No	:	WAUZZZ4M1JD048449
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	3-Aug-20
Place of Accident	:	Junction Of Paragon

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKQ 33 K

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer/reinstall front bumper wire harness for front parking aid system.	S/N \$	280.00	X
2	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$	560.00	✓
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$	450.00	X ✓
4	To dismantle front bumper. To renew lhs front fender, lhs front door and lhs rear door. Re-organise crash management components. Reinstall all parts removed.	\$	4,000.00	1000. 1,200.00
5	To respray lhs front fender, lhs front door and lhs rear door.	\$	4,000.00	1650 1,800.00
6	To renew lhs rear rim and carry out wheel alignment.	S/N \$	280.00	✓
7	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 9,762.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 33 K

S/N Parts Description		Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT FENDER - LH <i>Repair</i>	\$ 1,602.00	X
2	FRONT FENDER ATTACHMENT PARTS <i>all n</i>	\$ 75.00	+
3	FRONT FENDER WHEEL ARCH TRIM - LH / RH <i>all n</i>	2 \$ 654.00 327	261.20
4	FRONT DOOR - LH <i>Dented</i>	\$ 3,937.00	✓ 3,149.60
5	FRONT DOOR OUTER SEAL <i>all n</i>	NEC \$ 250.00	✓ 200.00
6	BONDING AGENT ?	NEC \$ 47.00	? X
7	CLEANING SOLUTION ?	NEC \$ 65.00	? X
8	FRONT DOOR CATCH <i>all n</i>	\$ 127.00	+
9	FRONT DOOR COVER - LH <i>cut</i>	\$ 447.00	✓ 357.20
10	REAR DOOR - LH <i>Dented</i>	\$ 3,937.00	✓ 3,149.60
11	REAR DOOR OUTER SEAL - LH <i>all n</i>	NEC \$ 247.00	✓ 197.60
12	BONDING AGENT ?	NEC \$ 47.00	? X
13	CLEANING SOLUTION ?	NEC \$ 65.00	? X
14	REAR DOOR ATTACHMENT PARTS ?	\$ 97.00	? X
15	REAR DOOR CATCH <i>all n</i>	\$ 104.00	+
16	REAR DOOR COVER - LH <i>cut</i>	\$ 593.00	✓ 474.00
17	EXTERIOR MIRROR MOUNTING - LH <i>all n</i>	\$ 1,491.00	+
18	REAR DOOR WHEEL ARCH TRIM - LH <i>all n</i>	\$ 121.00	✓ 96.40
19	REAR FENDER WHEEL ARCH TRIM - LH <i>all n</i>	\$ 194.00	+
20	REAR ALUMINIUM RIM - LH <i>Repair (polish)</i>	\$ 1,215.00	+
21	SUNDRIES ?	\$ 300.00	? ✓ 11.52
TOTAL SPARE PARTS CHARGES		: \$ 15,615.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian G
Surveyed Date : 06/08/00
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0540/2020/NS 18-Aug-20 Glory Tan 1 OF 1 SKQ 33 K Audi Q7 2.0 TFSI QU
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Rear door outer seal LHS 	\$ 189.00	151.20
TOTAL		\$ 189.00	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



For Premium Automobiles Pte Ltd

Authorised Signature