



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006667
INV Date 28/09/2020
Reference CC4/FCI20008133/R1es3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLV 3093D
Insured Veh. SHC 3229C
Claim No. D20003053MFSH
Policy No. D-20094922MFSH
Accident Date 01/08/2020
Inspection Date 06/08/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20008133/R1es3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 28-09-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 3229C	Veh. Inspected	SLV 3093D
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003053MFSH	Excess (\$)	0.00
Assign From	VIC	Assign Date	06/08/2020

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN SPORTSVAN 1.4	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WVWZZZAUZJW519090	Colour	BLUE
Odometer	67693	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	PIRELLI	6 mm
L/H Front Tyre	225/45 R17	PIRELLI	6 mm
R/H Rear Tyre	225/45 R17	PIRELLI	6 mm
L/H Rear Tyre	225/45 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	01/08/2020	Inspection Date	06/08/2020
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD NO 17 TUAS AVE 9 SINGAPORE 639197		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3093D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED REAR BUMPER	DEFORMED	1,175.85	1,175.85
1	REAR DIFFUSOR SATIN BLACK SPOILER	SERVICEABLE	323.62	-
1	BUMPER REINFORCEMENT	SERVICEABLE	619.61	-
1	ATTACHMENT STRIP BUMPER CENTRE BRACKET	SERVICEABLE	63.92	-
1	GUIDE PIECE (TAILLIGHT LOWER BRACKET LH)	SERVICEABLE	37.46	-
1	GUIDE PIECE (TAILLIGHT LOWER BRACKET RH)	SERVICEABLE	37.46	-
1	GUIDE PIECE BUMPER SIDE BRACKET LH	SERVICEABLE	37.46	-
4	BUMPER SIDE BRACKET RH POP-RIVET	NECESSARY	4.36	4.36
1	REVERSE SENSOR	SERVICEABLE	400.00	-
1	GUIDE PIECE BUMPER SIDE BRACKET RH	SERVICEABLE	37.46	-
			2,737.20	1,180.21
	<u>LABOUR</u>			
	DIAGNOTIC AND PROGRAMMING		480.00	480.00
	LABOUR .		2,520.00	840.00
	SPRAY PAINT.		2,400.00	800.00
			5,400.00	2,120.00
GRAND TOTAL			8,137.20	3,300.21

RECOMMENDED COST OF REPAIRS				3,300.21
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/FCI20008133/R1es3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 3093D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 3093D

RE-INSPECTION

