

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20008134/GES3Q2
Date: 22/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900139800
Claimant Vehicle No :	AU9644K	Insured Vehicle No :	SLK2467Z
Date of Loss:	20/01/2020	Nature of Claim:	TP
		Claim No:	0457395814SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	AU9644K	Engine No:	H976328
Make & Model:	TRIUMPH BONNEVILLE, 865cc	Chassis No:	SMTDAD85H4L974206
Reg. Date:	14/10/2019 (Man. Year: 2019)	Odometer:	3954 km
Colour:	Silver		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70ZR17	Rear Tyre Size:	160/60ZR17
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 9 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,422.25	7,060.55	2,361.70	25.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	500.00	510.00	50.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	10,432.25	7,560.55	2,871.70	27.53
+ GST 7.00/7.00% (\$\$)	730.26	529.24	201.02	27.53
Nett Amount (\$\$)	11,162.51	8,089.79	3,072.72	27.53
+ Loss of Use (3.0 x \$30.00/day) (\$\$)		90.00		
	Nett Liability (\$\$)	8,179.79		

INSPECTION

Date of Assignment:	06/08/2020		
Date Inspected:	06/08/2020	Inspected At:	Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

3/22/2021

Adjuster Report

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH EXHAUST MUFLER BLACK	Cut	1,260.00 FL	*1,260.00 FL
2	1		*EXHAUST LINK PIPE ,RH ,BRUSHED	Not Necessary	280.00 FL	*- FL
3	1		*EXHAUST HEADER RH BRUSHED	Cut	585.00 FL	*585.00 FL
4	1		*LINK PIPE GUARD COVER ,RH BRUSHED	Not Necessary	74.00 FL	*- FL
5	1		*RH FRONT FOOTREST	Cut	88.00 FL	*88.00 FL
6	1		*BANK ANGLE PEG ,RH FRONT FOOTREST	Cut	18.00 FL	*18.00 FL
7	1		*BRAKE PEDAL	Cut	170.00 FL	*170.00 FL
8	1		*TRIUMPH BADGE ,RH SIDE COVER ,BRUSHED	Not Necessary	66.00 FL	*- FL
9	1		*HEEL PLATE RH BRUSHED	Not Necessary	74.00 FL	*- FL
10	1		*RH THROTTLE BODY GUARD ,BRUSHED	Not Necessary	38.00 FL	*- FL
11	1		*RH THROTTLE BODY CAP ,BRUSHED	Not Necessary	31.00 FL	*- FL
12	1		*RH STATOR COVER ,MATT BLACK	Cut	314.00 FL	*314.00 FL
13	1		*PETROL TANK ,METALLIC GREY	Dented	2,455.00 FL	*2,455.00 FL
14	1		*RH MIRROR ,BAR END BLACK	Cut	92.00 FL	*92.00 FL
15	1		*RH BAR END ,BLACK	Broken	24.00 FL	*24.00 FL
16	1		*BRAKE LEVER ,TEC AFTERMARKET	Cut	170.00 FL	*170.00 FL
17	1		*THROTTLE ACTUATOR ASSY	Cut	272.00 FL	*272.00 FL
18	1		*FRONT BRAKE MASTER PUMP ASSY	Not Necessary	339.00 FL	*- FL
19	1		*HANDLEBAR	Cut	280.00 FL	*280.00 FL
20	1		*STEERING BRIDGE ,MATT METALLIC BLACK	Repair	324.00 FL	*- FL
21	1		*RH FRONT FORK ASSY	Repair	1,377.00 FL	*- FL
22	1		*METER BOTTOM COVER	Cut	199.00 FL	*199.00 FL
23	1		*RH FRONT SIGNAL ASSY	Cracked	110.00 FL	*110.00 FL
24	1		*RH FRONT BRAKE DISC	Cut	376.00 FL	*376.00 FL
25	5		*BOLTS ,RH FRONT BRAKE DISC	Necessary	60.00 FL	*60.00 FL
26	1		*TRIUMPH BADGE ,RH STATOR COVER	Necessary	7.50 FL	*7.50 FL
27	1		*HEADLAMP BODY	Cracked	169.00 FL	*169.00 FL
28	1		*GASKET ,STATOR COVER	Necessary	13.00 FS	*13.00 FS
29	1		*ACCESORY TIMING CAP ,MATT BLACK	Cut	66.00 FS	*66.00 FS
30	4		*LIT ENGINE OIL ,FULLY SYN LIQUI MOLY	Necessary	104.00 FS	*104.00 FS
31	1		*REAR NO PLATE EMBOSS	Bent	32.00 FS	*32.00 FS
32	1		*REAR TIRE ,160/60-17, PIRELLI ROSSO III	Scratched	189.00 FS	*170.00 FS
33	1		*BRAKE FLUID	Necessary	15.00 FS	*15.00 FS
34	1		*BRAKE SWITCH FRONT BRAKE	Broken	47.00 FS	*47.00 FS
35	1		*ERP UNIT	Distorted	156.00 FS	*156.00 FS
36	1		*ERP BRACKET	Bent	80.00 FS	*80.00 FS
37	1		*FLYSCREEN TRIUMPH ACCESSORY	Cracked	198.00 FS	*198.00 FS
38	1		*HEADLAMP GRILLE & BEZEL ,TRIUMPH ACCESSORY	Cut	195.00 FS	*195.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,347.50	7,725.50
- List Item Discount on L Items 10.00/10.00% (\$)	925.25	664.95
Total Parts (\$)	9,422.25	7,060.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING (TO REPORTING CENTRE,BACK TO WORKSHOP)	New	160.00	50.00
2	LABOUR CHARGE	New	850.00	450.00
Gross Labour Cost (S\$)			1,010.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >