



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20008140/Kqf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 30-10-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 4621G	Veh. Inspected	SMP 3192X
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002291/IJH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	06/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZVW400032274	Colour	WHITE
Odometer	98553	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	9 mm
L/H Front Tyre	205/60 R16	HANKOOK	9 mm
R/H Rear Tyre	205/60 R16	HANKOOK	9 mm
L/H Rear Tyre	205/60 R16	HANKOOK	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/08/2020	Inspection Date	07/08/2020
Survey held at	Messrs V8 Motor Werkz Pte Ltd-Block 7 #01-92		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**