



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT20002435	Page	1
	64 CECIL STREET	Date	: 5. Aug 2020		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZI007		
	SINGAPORE 049711	Svc Advisor	: RUEBEN THOMAS		
Registration No	: SJZ890S	Engine No	: K24Z15617908		
Chassis No	: JHLRE4850AC204161	Date Time	: 5. Aug 2020 1:14:43 PM		
Model	: CRV 2.4L 2010 MODEL	Surveyor Name	:		
Owner's Name	: LUI KIAN KEE	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 3/8/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: LUI KIAN KEE						
	OWNER INSURER: AXA INSURANCE						
	ACC DATE: 03/08/2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE						
	TP VEH: SH9102M						
BOSUN	SUNDRIES	1	50.00	100	50.00	3.50	53.50
BKFE22K	STRAIGHTEN ALIGN RR R FENDER & RR R DOOR	650	1400.00	350	1400.00	98.00	1498.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	520	1200.00	1040	1200.00	84.00	1284.00
	Sum Labor				2650.00	185.50	2,835.50

Survey By

Date & Time

Excess

Status

Signature

Total Amount 2,650.00 185.50 2,835.50

Total (Inclusive of GST) 2,835.50

Morais

28/8/20

No of Authorisation

Take photo before repair

3 days.

p/p \$1400

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/8/2020 1:17:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.