

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

Customer No.

: SQT20002435

Page 1

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

64 CECIL STREET

: JHLRE4850AC204161

: CRV 2.4L 2010 MODEL

#04-00 & #05-00 IOB BUILDING

SINGAPORE 049711

: INDIA INTERNATIONAL INSURANCE PTE

Svc Advisor

Date

Qty

: 5. Aug 2020 : WZI007

Engine No

: RUEBEN THOMAS

Date | Time

: K24Z15617908

Amount

Surveyor Name

5. Aug 2020 1:14:43 PM

Survey Date

Disc %

Authorisation Date

Unit Price

Ins Policy No. **Date of Accident**

Registration No

Owner's Name

Chassis No

Model

.

: 3/8/2020

: LUI KIAN KEE

: SJZ890S

0% GST **Amount**

Amount incld GST

Item Description TP DIRECT SETTLEMENT (J/NO:)

OWNER: LUI KIAN KEE

OWNER INSURER: AXA INSURANCE

ACC DATE: 03/08/2020

SURVEYED BY:

DATE: REF NO:

TP INSURER: INDIA INTERNATIONAL INSURANCE

TP VEH: SH9102M

BOSUN **SUNDRIES**

STRAIGHTEN ALIGN RR R FENDER & RR R DOOR SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 4

(2P)

50.00 1400.00

1200.00

50.00 1400.00

3.50 98.00

1498.00 1284.00

2,835.50

53.50

1200.00

Sum Labor

2650.00

84.00 185.50

Survey By

BKFE22K

BP02R

Date & Time

Excess

Total Amount

2,650.00 185.50

2,835.50

Status

Signature

Total (Inclusive of GST)

2,835.50

Printed on 5/8/2020 1:17:02 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00,

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.