

Not Autharik  
6/1 Sep 8

# **Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5150G**

**AAD2008-022**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 AUG 2020

**SHC 5150G**

VF1ABL15AUC276710

RENAULT

LATITUDE

4.8.2020

**CHINA TAIPING**

14/01/2014

| PART |                                   | LIST |                    |
|------|-----------------------------------|------|--------------------|
| 1    | BUMPER COVER REAR                 | \$   | Buc 561.70 ✓       |
| 1    | BUMPER LOWER REAR                 | \$   | Sn 411.90 X        |
| 1    | BUMPER BRACKET CTR REAR           | \$   | Sn 98.10 X         |
| 1    | BUMPER BRACKET SIDE RH REAR       | \$   | Dir 82.10 ✓        |
| 1    | BUMPER RETAINER RH REAR           | \$   | Dir 59.80 ✓        |
| 1    | BUMPER REFLECTOR RH               | \$   | Sn 16.60           |
| 1    | BUMPER BRACKET SIDE LH REAR       | \$   | Sn 80.80           |
| 1    | BUMPER RETAINER LH REAR           | \$   | Sn 54.20           |
| 1    | BUMPER REFLECTOR LH               | \$   | Sn 16.60           |
| 1    | BUMPER BEAM REAR                  | \$   | R 547.80           |
| 1    | BUMPER BEAM BRACKET LH REAR       | \$   | R 114.50           |
| 1    | BUMPER BEAM BRACKET RH REAR       | \$   | R 100.90           |
| 1    | BUMPER BLOCK RH REAR              | \$   | Sn 76.50           |
| 1    | BUMPER HARNESS REAR               | \$   | Sn 301.10          |
| 1    | OUTER PANEL REAR (End Panel)      | \$   | R 745.80           |
| 1    | OUTER PANEL REAR (End Panel) TRIM | \$   | Sn 404.56          |
| 1    | TAILLAMP RH                       | \$   | Br 401.40 ✓        |
| 1    | TAILLAMP PANEL RH                 | \$   | Br 401.40 ✓        |
| 1    | TAILLAMP LH                       | \$   | Sn 401.40 X        |
| 1    | TAILLAMP PANEL LH                 | \$   | R 401.40 X         |
| 1    | BOOT REAR                         | \$   | Br 1,677.20 ✓      |
| 1    | BOOT FINISHER                     | \$   | nap / Dir 344.70 ✓ |
| 1    | BOOT WEATHERSTRIP                 | \$   | Cr 178.20 50% ✓    |
| 1    | BOOT REFLECTOR LAMP LH            | \$   | Sn 277.70 X        |
| 1    | BOOT REFLECTOR LAMP RH            | \$   | Br 277.70 ✓        |
| 1    | BOOT BADGE 'RENAULT'              | \$   | Mr 82.40 ✓         |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5150G****AAD2008-022**

|                                      |           |                    |     |
|--------------------------------------|-----------|--------------------|-----|
| 1 BOOT BADGE                         | \$        | <i>Nu</i> 95.80    | ✓   |
| 1 BOOT STRUT LH                      | \$        | <i>Sn</i> 145.10   | X   |
| 1 BOOT TRIM BOARD                    | \$        | <i>Sn</i> 611.00   | X   |
| 1 BOOT STRUT RH                      | \$        | <i>Sn</i> 145.10   | X   |
| 1 BOOT HINGE LH                      | \$        | <i>R</i> 254.20    | X   |
| 1 BOOT HINGE RH                      | \$        | <i>R</i> 253.80    | ✓   |
| 1 BOOT LOCK                          | \$        | <i>R</i> 246.60    | X   |
| 2 BOOT RUBBER PLUG                   | \$        | <i>Sn</i> 139.30   | X   |
| 2 LICENCE PLATE LAMP                 | \$        | <i>Sn</i> 26.30    | X   |
| 1 BOOT SWITCH                        | \$        | <i>Sn</i> 113.00   | X   |
| 1 EXHAUST REAR                       | \$        | <i>R</i> 5,263.60  | X   |
| 1 REAR RH FENDER PANEL               | \$        | <i>Sn</i> 1,933.20 | ✓   |
| 1 WHEELARCH REAR RH                  | \$        | <i>Sn</i> 275.40   | } X |
| 1 FENDER PANEL INNER TRIM REAR RH    | \$        | <i>R</i> 671.45    |     |
| 1 SPARE WHEEL PANEL                  | \$        | <i>R</i> 1,229.40  |     |
| 1 SPARE WHEEL PANEL TRIM             | \$        | <i>Sn</i> 612.21   |     |
| 1 SPARE TYRE BOARD                   | \$        | <i>Sn</i> 680.90   |     |
| 1 CHASSIS PANEL REAR RH              | \$        | <i>R</i> 2,192.40  |     |
| 1 FENDER PANEL INNER REAR RH L70Y    | \$        | <i>R</i> 1,241.60  |     |
| 1 FENDER INNER BOARD RH L70Y         | \$        | <i>Sn</i> 561.40   |     |
| 1 FENDER WHEEL HOUSING PANEL REAR RH | \$        | <i>R</i> 4,682.09  |     |
| <b>TOTAL</b>                         | <b>\$</b> | <b>29,490.31</b>   |     |
| <b>10%</b>                           | <b>\$</b> | <b>2,949.03</b>    |     |
|                                      | <b>\$</b> | <b>26,541.28</b>   |     |

**Special Nett**

|                                     |    |                  |     |
|-------------------------------------|----|------------------|-----|
| 1SET PARKING AID                    | \$ | <i>Sn</i> 700.00 | X   |
| 1SET REAR BUMPER CLIP               | \$ | <i>Nu</i> 75.00  | ✓   |
| 1SET BUMPER BRACKET CTR CLIP        | \$ | <i>Nu</i> 55.00  | } X |
| 1SET BUMPER BRACKET SIDE CLIP RH RR | \$ | <i>Nu</i> 60.00  |     |
| 1SET BUMPER RETAINER RH CLIP RR     | \$ | <i>Nu</i> 65.00  |     |
| 1SET BUMPER BRACKET SIDE CLIP LH RR | \$ | <i>Nu</i> 60.00  |     |
| 1SET BUMPER RETAINER CLIP LH RR     | \$ | <i>Nu</i> 65.00  |     |
| 1SET BUMPER LOWER REAR RIVET        | \$ | <i>Nu</i> 70.00  |     |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5150G****AAD2008-022**

|                                     |           |            |                  |               |
|-------------------------------------|-----------|------------|------------------|---------------|
| 1SET BUMPER LOWER REAR CLIP         | \$        | <i>nn</i>  | 75.00            | ✓             |
| 1 BOOT STICKER "Trans-cab"          | \$        | <i>nn</i>  | 80.00            | <i>305n</i>   |
| 1 BOOT STICKER "6555-3333"          | \$        | <i>nn</i>  | 80.00            | <i>305n</i>   |
| 1SET BOOT FINISHER CLIP             | \$        | <i>nn</i>  | 55.00            | X             |
| 1 TAILLAMP CLIP LH                  | \$        | <i>nn</i>  | 40.00            | X             |
| 1 TAILLAMP CLIP RH                  | \$        | <i>nn</i>  | 40.00            | <i>5.00</i> ✓ |
| 1 Rear Bumper Protector             | \$        | <i>nsp</i> | 180.00           | X             |
| 1 REAR LICENCE PLATE WITH HOLDER    | \$        | <i>sn</i>  | 130.00           | X             |
| 1 EXHAUST MOUNTING                  | \$        | <i>sn</i>  | 60.00            | X             |
| 1 FENDER INNER TRIM CLIP RH         | \$        | <i>nn</i>  | 55.00            | X             |
| 1SET FENDER WHEELARCH REAR RH CLIP  | \$        | <i>nn</i>  | 65.00            | X             |
| 2 REAR WINDSCREEN SEALANT           | \$        | <i>nn</i>  | 150.00           | <i>405n</i> ✓ |
| 1 WINDSCREEN MOULDING               | \$        | <i>nn</i>  | 200.00           | X             |
| 1 REAR WINDSCREEN INNER SPONGE SEAL | \$        | <i>nn</i>  | 130.00           | <i>305n</i>   |
| 2 SEAM SEALANT                      | \$        | <i>nn</i>  | 170.00           | X             |
| 1 RENAULT TYRE 215/60/16            | \$        | <i>sn</i>  | 330.00           | X             |
| 1 RENAULT TYRE RIM                  | \$        | <i>sn</i>  | 380.00           | X             |
| 1 SPARE TYRE                        | \$        | <i>sn</i>  | 330.00           | X             |
| 1SET END PANEL TRIM CLIP            | \$        | <i>nn</i>  | 55.00            | X             |
| <b>TOTAL</b>                        | <b>\$</b> |            | <b>3,755.00</b>  |               |
| <b>TOTAL PARTS</b>                  | <b>\$</b> |            | <b>30,296.28</b> |               |

**LABOUR**

|                                                                                               |    |           |        |            |
|-----------------------------------------------------------------------------------------------|----|-----------|--------|------------|
| To check steering geometry and computer wheel alignment                                       | \$ | <i>nn</i> | 220.00 | X          |
| To drop rear exhaust box, renew the same, to repair and realign rear and centre exhaust pipe. | \$ | <i>nn</i> | 380.00 | X          |
| To transfer of bootlid fittings, attachments and perform water seepage test.                  | \$ |           | 170.00 | <i>601</i> |
| Towing Fees                                                                                   | \$ | <i>nn</i> | 150.00 | X          |

**Trans-cab Auto Services Pte Ltd****AAD2008-022**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5150G**

|                                                                                                                           |    |    |          |      |
|---------------------------------------------------------------------------------------------------------------------------|----|----|----------|------|
| To transfer of rear bumper fittings, attachment and perform water seepage test.                                           | \$ | nn | 170.00   | X    |
| To transfer of rear end panel fittings, attachment and perform water seepage test.                                        | \$ |    | 380.00   | 100% |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ |    | 2,800.00 | 800% |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | nn | 380.00   | X    |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | ↪  | 170.00   | X    |
| To transfer of rear fender fittings, attachment and perform water seepage test.                                           | \$ | ↪  | 170.00   | X    |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                           | \$ | ↪  | 380.00   | X    |
| To transfer of rear windscreen glass to facilitate bodywork repair.                                                       | \$ |    | 170.00   | 120% |
| To Check Electrical Lighting Concerned.                                                                                   | \$ |    | 170.00   | 20%  |
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                                               | \$ |    | 250.00   | 60%  |
| To supply and re-do rear luggage floor panel insulation padding.                                                          | \$ | ↪  | 380.00   | X    |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.       | \$ | ↪  | 380.00   | X    |

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5150G****AAD2008-022**To transfer of rear luggage floor panel fittings,  
attachment and perform water seepage test.

\$ 380.00 X

Putty and spray painting of the affected portion.

\$ 2,800.00 8801

To reinstall rear bumper parking sensor.

\$ 170.00 601

**TOTAL \$ 10,070.00****Over All Total \$ 40,366.28****LUMP SUM ( REPAIR DAY)****25 DAYS****6 days****For Official Use**Prepared By : \_\_\_\_\_  
(Accident Dept)Verify By : \_\_\_\_\_  
(Accident Workshop)Checked By : \_\_\_\_\_  
(Finance Dept)LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: