

ASS. REC. BY:

REF:

Smo/ 2000 8156/KVf3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 832k \$34k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 21 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

7/8 Check LTA rebate & let me know

Date/Time, File Pass to?

Prell. Report

1)

Date/Time, File Return to?

Final Report

11/8/20-Typist

Report Format: Uneconomical T/L

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee: Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Fees

Others

TOTAL

Veh No:

SKV 4129R Yr Regn: 09, 15

Type: M.Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Atarak c.c. 1193

Colour

M. Silver A/C: Insured / Std / NI / NA

Sp. Reading

7370 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MMB STA13A FH 013714

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 185/55R15

R:

SS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

R/Bal.

8 mm

Rear

R/Bal.

8 mm

L/Bal.

8 mm

L/Bal.

8 mm

D.O.A.

2/8/20

D.O.I.

7/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S & Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Not Authorised
 11 Days @
 Recovery After Paim
 21 days



ESTIMATE TO REPAIR

VEHICLE NO. : SKV 4119 R
 MAKE : MITSUBISHI
 MODEL : ATTRAGE 1.2 CVT
 YEAR : 2015
 CHASSIS NO : MMBSTA13AFH013714

SURVEYOR NAME : *[Signature]*
 DATE OF SURVEY : 07-08-20
 TIME OF SURVEY : *[Signature]*

DATE : 06-Aug-20
 DATE OF ACCIDENT : 02-Aug-20
 THIRD PARTY REF : SKJ4929L / SOMPO INSURANCE

No.	Parts Description / Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Front Bumper			<i>B1/cm</i> \$ 666.00	
1 pc	Front Bumper Tow Cover			<i>RM</i> \$ 15.00	
1 pc	Front Bumper Reinforcement			<i>R1</i> \$ 130.00	
2 pcs	Front Bumper Retainer		\$ 20.00	<i>ols cm</i> \$ 40.00	
1 sets	Front Bumper Lower Spoiler			<i>R</i> \$ 1,600.00	
1 pc	Front Bumper Lower Grille			\$ 156.00	
1 pc	Front Bumper RH Fog Lamp			\$ 274.00	
1 pc	Front Bumper RH Fog Lamp Cover			<i>RM</i> \$ 120.00	
10 pcs	Front Bumper Clips		\$ 3.00	<i>RM</i> \$ 30.00	
1 pc	Front Grille			<i>RM</i> \$ 525.00	
1 pc	Front Support Panel			\$ 999.00	
1 pc	RH Head Lamp			<i>CM</i> \$ 544.00	
1 pc	Bonnet			<i>R1</i> \$ 681.00	
1 pc	Front RH Fender			<i>R1</i> \$ 438.00	
1 pc	Front RH Fender Under Shield			<i>CM</i> \$ 93.00	
6 pcs	Front RH Fender Under Shield Clip		\$ 3.00	<i>RM</i> \$ 18.00	
1 pc	Washer Tank			<i>RM</i> \$ 67.00	
1 pc	Front RH Shock Absorber			\$ 428.00	
1 pc	Front RH Knuckle Arm			\$ 329.00	
1 pc	Front RH Knuckle Bearing			\$ 114.00	
1 pc	Front RH Lower Arm			\$ 304.00	
1 pc	Rear Bumper			<i>mi</i> \$ 708.00	
2 pcs	Rear Bumper Retainer		\$ 26.00	<i>RM</i> \$ 52.00	
2 pcs	Rear Bumper Bracket		\$ 20.00	\$ 40.00	
10 pcs	Rear Bumper Clips		\$ 3.00	<i>RM</i> \$ 30.00	
2 pcs	Rear Bumper Sensor		\$ 300.00	<i>mi</i> \$ 600.00	
1 pc	Rear End Panel			<i>R1</i> \$ 402.00	
1 pc	Rear End Panel Garnish			<i>SM</i> \$ 70.00	
2 pcs	Tail Lamp		\$ 276.00	<i>ols RM</i> \$ 552.00	
1 pc	Rear Boot Lid			<i>R</i> \$ 828.00	
1 pc	Rear RH Fender			<i>R1</i> \$ 723.00	
	BAL C/F				\$ 11,576.00

[Handwritten notes and calculations on the right margin, including 'x 4', 'x 2', 'x 3', 'x 4', 'x 5', 'x 6', 'x 7', 'x 8', 'x 9', 'x 10', 'x 11', 'x 12', 'x 13', 'x 14', 'x 15', 'x 16', 'x 17', 'x 18', 'x 19', 'x 20', 'x 21', 'x 22', 'x 23', 'x 24', 'x 25', 'x 26', 'x 27', 'x 28', 'x 29', 'x 30', 'x 31', 'x 32', 'x 33', 'x 34', 'x 35', 'x 36', 'x 37', 'x 38', 'x 39', 'x 40', 'x 41', 'x 42', 'x 43', 'x 44', 'x 45', 'x 46', 'x 47', 'x 48', 'x 49', 'x 50', 'x 51', 'x 52', 'x 53', 'x 54', 'x 55', 'x 56', 'x 57', 'x 58', 'x 59', 'x 60', 'x 61', 'x 62', 'x 63', 'x 64', 'x 65', 'x 66', 'x 67', 'x 68', 'x 69', 'x 70', 'x 71', 'x 72', 'x 73', 'x 74', 'x 75', 'x 76', 'x 77', 'x 78', 'x 79', 'x 80', 'x 81', 'x 82', 'x 83', 'x 84', 'x 85', 'x 86', 'x 87', 'x 88', 'x 89', 'x 90', 'x 91', 'x 92', 'x 93', 'x 94', 'x 95', 'x 96', 'x 97', 'x 98', 'x 99', 'x 100']

Lim Tan Motor Pte Ltd
 Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
 Tel: 65-64520893 Fax: 65-64589127 Email: edmund@LTM.sg Website: www.LTM.sg
 Co.Reg No. 199307277D GST Reg No. M2-0019086-0
 This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

	Bal C/F				\$11,576.00	
1 pc	Rear RH Fender Under Shield				CM \$38.00	1
1 pc	Rear Attridge Emblem				MC \$38.00	1
1 pc	Rear Boot Centre Emblem				MC \$41.00	1
1 pc	MIVEC Emblem				MC \$41.00	1
1 pc	Rear Exhaust Silence Box				MC \$571.00	1
1 pc	Exhaust Centre Pipe				\$852.00	7
1 pc	Exhaust Tail Pipe				\$742.00	7
2 pcs	Exhaust Mounting		\$24.00		Ta \$48.00	1
1 pc	Rear RH Shock Absorber				MC \$188.00	1
1 pc	Rear RH Wheel Bearing				MC \$114.00	1
1 pc	Rear Axle				MC \$939.00	1
1 pc	Sport Rim				\$719.00	7
	Less 20%				\$15,907.00	
					\$3,181.40	
					\$12,725.60	
1 pc	Tyre	Rec Pu	S.Nett	\$250.00	\$500.00	80/144
1 tube	Rear Windscreen Sealant		S.Nett		MC \$40.00	1
	To Putty & Spray Paint Towing.				\$2,400.00	1800
	To Check Front Wiring and Focus Head Light.				\$100.00	7
	To Replace Air Con Condenser & Top Up Gas.				\$30.00	1
	To Replace Front Under Carriage.				\$100.00	7
	To Replace Rear Under Carriage.				\$300.00	7
	To Check Wheel Alignment.				\$280.00	2401
	To Remove & Refix Cushion Seat & Trimming.				\$80.00	1
	To Remove & Refix Rear Windscreen Glass.				\$120.00	1
	To Anti-Rust.				\$120.00	1
	Labour Charges				\$150.00	1201
					\$2,400.00	2000
TG-TH/-	TOTAL				\$ 19,345.60	

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website : www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/08/2020 15:39
Date Of Accident	02/08/2020 19:40
Exact Location Of Accident	ALONG PUNGGOL EAST TWDS PUNGGOL CTRL AT EXTM LEFT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV4129R
Insured/Policyholder	
Name Of Registered Owner	CHEN SIYA
NRIC No	SXXXX140B
Email Address	CHENSIYA87@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96332803
Alternative Phone No	OFFICE-96332803

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE-1.2 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100781285
Cover Note Number	

Driver

Name of Driver	TEY TZE TONG
NRIC No	SXXXX425E
Date Of Birth	18/09/1986
Occupation	INDOOR
Date Of Driving Pass	25/04/2005
Driving Experience	15 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96823991
Fax Number	
Contact Number	
Email Address	TZETONG3@GMAIL.COM

Address 10 LENTOR GREEN S 789259
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured SPOUSE
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1 NAME: : WIFE
GENDER: : FEMALE
Passenger 2 NAME: : SON
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name PUNGGOL N.P.C
Police Station Address ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT T/20200803/2082

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHC7042Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver



SINGAPORE POLICE FORCE



T/20200803/2082

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No. T/20200803/2082

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/08/2020 16:42		Vide Report No.:		Station Diary No.: 55	
Informant's Particulars					
Name of Informant: TEY TZE TONG			Address: 10 LENTOR GREEN SINGAPORE 789259		
ID Type / ID No.: NRIC NO / S8625425E			Contact No.: Home/Office:		Mobile: 96823991
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 33	Date of Birth: 18/09/1986	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: DOCTOR			Driving Licence Information: Class: 2B,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/08/2020 19:40	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 PUNGGOL EAST PUNGGOL CENTRAL Along Punggol East towards Punggol Central at the extreme left lane				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC7042Y	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Yellow	Seriously Damaged	0
SKV4129R	Car	MITSUBISHI	ATTRAGE 1.2 CVT	Silver	Seriously Damaged	2



**SINGAPORE
POLICE FORCE**



T202008032052

2 of 3

Report No. T202008032052

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE S28837
Tel No: 1800-6049999

CONTINUATION OF REPORT

Brief Details.

On 02/08/2020 at about 1940hrs, I was driving my vehicle SKV4129R along Punggol East towards Punggol Central at the extreme left lane with my wife who is pregnant for 38 weeks and 2 year old son. Both my wife and my son was sitting at the rear passenger seat.

Suddenly the vehicle SHC7042Y which is in front of my vehicle made an emergency brake and I immediately applied emergency brake too and I manage to stop in time before hitting his vehicle. Suddenly, I felt a huge impact from the rear of my vehicle which resulted my vehicle protruded forward and hit against the front vehicle SHC7042Y.

I then check with my wife and my son if they are alright. My wife informed that she had right shoulder pain and my son was alright at that point of time. I then got out of my vehicle and carried my son out and my wife also came out of the vehicle to make a check. We saw that there's a vehicle had overturned at the front middle lane and there are lots of people at the scene. One of the passerby informed me that he had already called for an ambulance. I then asked my wife to sit at the bus stop seat near the accident site with my son and wait for ambulance. I then called my mother-in-law and inform about the matter and they came down to the scene afterwards.

Ambulance, police and fireman came to the scene. The paramedics render medical assistance to us and my wife. Traffic police took my details and my wife was conveyed to KK Hospital accompanied with me and I handed my son to my mother-in-law to take care. After a while, traffic police contacted me and informed me that they will tow my vehicle. They also gave me a case number F/20200802/0250.

When, I was at KK Hospital and the doctor made a check on my wife. The doctor told us that during the check, they notice the baby heartbeat had slow down for awhile and recommended my wife to deliver our baby early as they are worry. We are worried for our baby, we agreed to my wife to deliver our baby early and KK Hospital kept us in observation till 7am.

On 03/08/2020 at 0700hrs, my wife was discharge from KK Hospital and we went to Mount Elizabeth Novena Hospital for my wife to deliver our baby.