

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China Taiping UFS
LKK-Taufik

Date: 05.08.2020

Time: 11:21:04

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305414815
 REGN NO : SHC 333D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 05.08.2020 10:15
 ACCIDENT DATE : 28.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	de ✓
0002 04-01-0103-2164-A	RADIATOR GRILLE	1	1,480.00	20.00	1,184.00	an ✓
0003 04-01-0103-2175-G	RADIATOR GRILLE EMBLEM	1	39.50	20.00	31.60	nee ✓
0004 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de ✓
0005 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	RY ✓
0006 04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60	nee ✓
0007 09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	nvd ✓
0008 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00		50.00	nee ✓
0009 FNPS	NO PLATE(S)-FRT W/Trim Cover 1 L	55.00			55.00	(rq) ✓

SUB-TOTAL : 3,382.86

JOB NATURE

0000 PB	PANEL BEATING	600.00	560
0001 SP	SPRAYPAINT CHARGE	500.00	400

SHC 1037G

SHA7029Y

COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.08.2020

REPAIR ESTIMATE

China Taiping (45)

Time: 11:21:04

Page: 2

IS

Lkk - Taufik

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305414815

REGN NO : SHC 333D

MILEAGE : 0000000000

MAKE : HYUNDAI

MODEL : I-40

DATE OF REGN : 17.03.2016

DATE/TIME IN : 05.08.2020 10:1

ACCIDENT DATE : 28.07.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0002 L

R/I REVERSE SENSOR

120.00 30

SUB-TOTAL : 1,220.00

TOTAL : 4,602.86

Lmk

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Taufik 9749849
- WP' 5/8/2020 3pm

Lmk psum 3 days

Resurvey after repair

Taufik Chhantian.
Westlake.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 05.08.2020 10:43

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305414815

OWNER
CITYCAB PTE LTD
7010070
OMER NO.
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
(R) (O)
(P)

REGN NO.	SHC 333D	MILEAGE
MAKE :	HYUNDAI	FUEL E.....1/2.....F
MODEL	I-40	DATE/TIME IN 05.08.2020 10:15
YR OF MANU.	17.03.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU085551	COMPLETION DATE/TIME:


OUNT CARD NO.

JOB DESCRIPTION

Accident Date: 28.07.2020
NATURE: 3P 28.07.2020

Fr & Rear

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

Exit Pass

SHC 333D

LIMITS

Vehicle No.:

SHC 333D

Service Advisor

Signature/Date

Name of Service Advisor

Date