



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006413
INV Date 16/09/2020
Reference CC4/FCI20008158/Dda3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKT 2961C
Insured Veh. SHD 6859J
Claim No. D20003054MFSH/1
Policy No. D-20094922MFSH
Accident Date 03/08/2020
Inspection Date 05/08/2020

Description	Total
Third Party Express Settlement	600.00
Subtotal	600.00
GST (7%)	42.00
Grand Total	642.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20008158/Dda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 16-09-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 6859J	Veh. Inspected	SKT 2961C
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20003054MFSH/1	Excess (\$)	0.00
Assign From	JASON TEA	Assign Date	05/08/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN SYLPHY	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0022661	Colour	SILVER
Odometer	89709	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/60 R16	YOKOHAMA	5 mm
L/H Front Tyre	195/60 R16	YOKOHAMA	5 mm
R/H Rear Tyre	195/60 R16	YOKOHAMA	5 mm
L/H Rear Tyre	195/60 R16	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	03/08/2020	Inspection Date	05/08/2020
Survey held at	GOH LEE HWA AUTOMOBILE PTE LTD BLK.5033 #01-255 ANG MO KIO INDUSTRIAL PARK 2 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2961C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAIL BOOT (N)	BENT / DENTED	1,288.00	1,163.80
1	TAIL BOOT SPOILER (N)	NOT NECESSARY	966.50	-
1	TAIL BOOT LOGO (N)	NECESSARY	59.10	59.10
1	TAIL BOOT SYLPHY EMBLEM (N)	NECESSARY	99.70	99.70
1	TAIL BOOT SIGNATURE EMBLEM (N)	NECESSARY	69.70	69.70
1	TAIL BOOT ADVANCED EMBLEM (N)	NECESSARY	69.70	69.70
1	TAIL BOOT CHROME (UPPER)(N)	SERVICEABLE	208.80	-
1	TAIL BOOT CHROME (LOWER)(N)	BENT	145.90	145.90
2	TAIL BOOT LAMP @\$181.40 (N)	MOUNTING CRACKED	362.80	362.80
2	TAIL FENDER LAMP @\$405.70 (N)	MOUNTING CRACKED	811.40	761.00
1	TAIL BOOT LOCK (N)	BENT	78.50	78.50
1	REAR BUMPER (N)	DENTED	689.30	607.00
2	REAR BUMPER BRACKET @\$59.90 (N)	NOT NECESSARY	119.80	-
2	REAR BUMPER REFLECTOR @\$65.00 (N)	N/S BROKEN / O/S NOT NECESSARY	130.00	65.00
2	REAR BUMPER EXHAUST CHROME @\$260.00 (N)	N/S CUT / O/S NOT NECESSARY	520.00	260.00
2	REAR BUMPER SIDE CATCH @\$45.90 (N)	SERVICEABLE	91.80	-
1	REAR BUMPER LOWER SPOILER (N)	BENT	299.50	299.50
1	REAR BUMPER SPONGE CENTRE (N)	TORN	56.30	56.30
2	REAR BUMPER SIDE SPONGE @\$156.00 (N)	TORN	312.00	175.80
1	REAR END PANEL (N)	DENTED	695.00	561.60
1	TAIL BOOT CARPET (N)	BENT / DEFORMED	289.00	138.80
2	TAIL BOOT HINGE RH/LH @\$198.00 (N)	TO REPAIR SEE LABOUR	396.00	-
1	TAIL BOOT KEY LOCK (N)	NOT NECESSARY	210.00	-
1	REAR END PANEL GARNISH (N)	DEFORMED	296.30	109.10
1	REAR SPARE TYRE BOARD (N)	BENT	499.00	356.60
1	REAR FENDER N/S (N)	TO REPAIR SEE LABOUR	1,590.00	-
2	REAR FENDER DUST GARNISH @\$180.00 (N)	NOT NECESSARY	360.00	-

Report Ref No. CC4/FCI20008158/Dda3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	REAR FENDER DUST GARNISH CLIPS @\$5.00 (N)	NOT NECESSARY	40.00	-
1	NUMBER PLATE & BOX (N)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN INNER SEAL (N)	NOT NECESSARY	90.00	-
1	REAR WINDSCREEN REPAIR KIT (N)	NOT NECESSARY	180.00	-
1	REAR WEATHER SLIP (N)	DEFORMED	248.00	101.50
1	SPARE TYRE PANEL (ADDITIONAL)(N)	DENTED	1,100.00	956.20
1	SPARE TYRE SPONGE (ADDITIONAL)(N)	BROKEN	599.00	385.20
2	SPARE TYRE TUBE COAT @\$180.00 (ADDITIONAL)(N)	NOT NECESSARY	360.00	-
	LESS 10% DISCOUNT		-	-688.28
			13,381.10	6,194.52
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS @\$3.00 (SN)	NECESSARY	30.00	15.00
1	SET REAR BUMPER PARKING SENSOR (SN)	DAMAGED	280.00	220.00
10	TAIL BOOT CARPET CLIPS @\$5.00 (SN)	NECESSARY	50.00	15.00
4	REAR END PANEL GARNISH CLIPS @\$5.00 (SN)	NECESSARY	20.00	10.00
			380.00	260.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		120.00	30.00
	TO REMOVE & REFIT REAR WINDSCREEN.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT INTERIOR GARNISH,SIDE BOARD & ALL AFFECTED AREA.		200.00	120.00
	TO KNOCKING,STRAIGHTENING REPAIR & RENEW ALL ACCIDENT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF TAIL BOOT HINGE RH/LH AND REAR FENDER N/S.		1,200.00	900.00
	TO RESPRAY PAINTING ON ALL ACCIDENT AFFECTED AREA.		1,000.00	900.00
	TO RUST PROOF ALL ACCIDENT AFFECTED AREA.		120.00	40.00
			-	-
			-	-
			-	-
			2,820.00	1,990.00
GRAND TOTAL			16,581.10	8,444.52

Report Ref No. CC4/FCI20008158/Dda3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,500.00
---	--	--	-----------------

Report Ref No. CC4/FCI20008158/Dda3q2

A handwritten signature in black ink, appearing to be 'Ang Bryan Tani'.

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 2961C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKT 2961C

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

