

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 40820**Date: 04.08.2020****Aik Chin Hin (Kaki Bukit) Pte Ltd****13 Kaki Bukit Rd 4 #03-05 Bartley Biz Centre****Singapore 417807****Nissan Sylphy****Estimated Repair Cost for Vehicle Reg. No: SKT 2961 C****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Tail Boot	1st / Dent		1,288.00 Nett.	✓
1 Pc. Tail Boot Spoiler	SVC		966.50 Nett.	X
1 Pc. Tail Boot Logo	Hec		59.10 Nett.	✓
1 Pc. Tail Boot Sylphy Emblem	Hec		99.70 Nett.	✓
1 Pc. Tail Boot Signature Emblem	Hec		69.70 Nett.	✓
1 Pc. Tail Boot Advanced Emblem	Hec		69.70 Nett.	✓
1 Pc. Tail Boot Chrome (Upper)	SVC		208.80 Nett.	X
1 Pc. Tail Boot Chrome (Lower)	1st		145.90 Nett.	✓
2 Pcs. Tail Boot Lamp	mounting crack	@ 181.40	362.80 Nett.	✓
2 Pcs. Tail Fender Lamp	mounting crack	@ 405.70	811.40 Nett.	✓
1 Pc. Tail Boot Lock	1st		78.50 Nett.	✓
1 Pc. Rear Bumper	Dent		689.30 Nett.	✓
2 Pcs. Rear Bumper Bracket	NH	@ 59.90 Nett.	119.80 Nett.	X
2 Pcs. Rear Bumper Reflector	N/S broken	@ 65.00 Nett. o/s NH	130.00 Nett.	✓
10 Pcs. Rear Bumper Clips	Hec	@ 3.00 Nett.	30.00 Nett.	✓
1 Set. Rear Bumper Parking Sensor	Dent		280.00 S. Nett.	✓ 220.00 SW
2 Pcs. Rear Bumper Exhaust Chrome		@ 260.00 Nett.	520.00 Nett.	✓ N/S cut o/s NH
2 Pcs. Rear Bumper Side Catch	SVC	@ 45.90 Nett.	91.80 Nett.	X
1 Pc. Rear Bumper Lower Spoiler	1st	@ 299.50 S. Nett.	299.50 S. Nett.	✓
1 Pc. Rear Bumper Sponge Centre	turn		56.30 Nett.	✓
2 Pcs. Rear Bumper Side Sponge	turn	@ 156.00 Nett.	312.00 Nett.	✓
1 Pc. Rear End Panel	Dent		695.00 Nett.	✓
1 Pc. Tail Boot Carpet	1st / damaged		289.00 Nett.	✓
10 Pcs. Tail Boot Carpet Clips	Hec	@ 5.00	50.00 Nett.	✓
2 Pcs. Tail Boot Hinger	RH/LH	@ 198.00	396.00 Nett.	X
1 Pc. Tail Boot Key Lock	NH		210.00 Nett.	X
1 Pc. Rear End Panel Garnish	damaged		296.30 Nett.	✓
4 Pcs. Rear End Panel Garnish Clips	Hec	@ 5.00	20.00 Nett.	✓

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Rear Spare Tyre Board <i>1st</i>		499.00 Nett. ✓
1 Pc. Rear Fender <i>4/5 Veyu</i>		1,590.00 Nett. ✗
2 Pcs. Rear Fender Dust Garnish <i>HW</i>	@ 180.00	360.00 Nett. ✗
8 Pcs. Rear Fender Dust Garnish Clips <i>HW</i>	@ 5.00	40.00 Nett. ✗
1 Pc. Number Plate & Box <i>HW</i>		50.00 Nett. ✗
1 Pc. Rear Windscreen Inner Seal <i>HW</i>		90.00 Nett. ✗
1 Pc. Rear Windscreen Repair Kit <i>HW</i>		180.00 ✗
1 Pc. Rear weather slip <i>detached</i>		248.00 Nett. ✓

Total (Panels / Parts):**11,702.10 (SGD)***List 30% Nett 10%***LABOR CHARGES**

To check wiring.	120.00 <i>30/-</i>
To Remove & refit rear windscreen	180.00 <i>HW</i>
To remove & refit interior garnish, side board & all affected area.	200.00 <i>120/-</i>
To knocking, straightening repair & renew All accident affected area.	1200.00 <i>900/-</i>
To respray painting on all accident affected area.	1000.00 <i>900/-</i>
To rust proof all accident affected area.	120.00 <i>40/-</i>

Total (Labor Charges):**2,820.00 (SGD)***05/08/2020**HA Antun**2/3mm 5 days.**Ryan***TOTAL COST SUMMARY***LKK Auto*LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

PANELS / PARTS
LABOR CHARGES

11,702.10

2,820.00

Grand Total: 14,522.10 (SGD)

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'



GOH LEE HWA AUTOMOBILE PTE LTD

[WITHOUT PREJUDICE SAVE AS TO COSTS]