

# SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

Not Authorized  
6/1/2008 @ 3000h  
Preserving After Pain  
5 days

Insurance: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Owner: JOHAN TEH BIN ABDULLAH

Registration no. FX982T/HONDA NF125MD/NF125MD5001900

Date: 6-Aug-20

Quotation no.: 070820

| S/N        | Qty | Item                                  | Amount          |
|------------|-----|---------------------------------------|-----------------|
| LIST ITEMS |     |                                       |                 |
| 1          | 1   | Front fender                          | Dis/ln 230.00 ✓ |
| 2          | 1   | Bracket comp front fender             | R 88.00 x       |
| 3          | 1   | Front wheel axle                      | 4 106.90 ✓      |
| 4          | 1   | Front RH fork assy                    | sn 495.00 x     |
| 5          | 1   | Front LH fork assy                    | ln 495.00 x     |
| 6          | 1   | Front RH disc rotor                   | way 230.00 ✓    |
| 7          | 1   | Front fork steering stem with bearing | At/ln 450.00 ✓  |
| 8          | 1   | Front cover assy RH                   | cm 380.20 ✓     |
| 9          | 1   | Stay front cover                      | cm 450.00 ✓     |
| 10         | 1   | Head lamp Assy -center                | ln 440.00 ✓     |
| 11         | 1   | Left switch assy                      | sn 128.40 x     |
| 12         | 1   | Right switch assy                     | cm 145.00 ✓     |
| 13         | 1   | Center box cover                      | cm 188.60 ✓     |
| 14         | 1   | LH fairing cover                      | sn 55.00 x      |
| 15         | 1   | RH fairing cover                      | Dis 55.00 ✓     |
| 16         | 1   | Steering handle bar                   | Dis 195.00 ✓    |
| 17         | 2   | Balancer \$45 each                    | ols/ln 90.80 ✓  |
| 18         | 1   | LH view mirror                        | At/ln 145.00 ✓  |
| 19         | 1   | Side stand                            | Dis 105.00 ✓    |
| 20         | 1   | Main stand                            | R 335.00 x      |
| 21         | 1   | Cover set <sup>ctral</sup> LH body    | ln 590.00 x     |
| 22         | 1   | LH handle cover                       | sn 175.20 x     |
| 23         | 1   | Headlamp support bracket              | R 45.00 x       |
| 24         | 1   | RH view mirror                        | At/ln 75.80 ✓   |
| 25         | 1   | Meter cover assy                      | sn 145 220.00 x |
| 26         | 1   | Helmet                                | cm 88.00 750.00 |

6001.90

LESS 10%

600.19

5401.71

With  
ERP, braket. - 220. mis ✓

Front ctal basket - 110 mycm

**SERVE YOU MOTOR SERVICE**  
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2  
 #01-265, SINGAPORE 569536  
 TEL. NO: 64810555 / FAX NO. 64831654  
 E-MAIL: elainesyms@gmail.com

Ins: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 Owner: JOHAN T EH BIN ABDULLAH  
 Registration no. FX982T/HONDA NF125MD/NF125MD5001900  
 Date 6-Aug-20

Quotation no.: 070820

Pg 2

| S/N                       | Qty | Item                  | Amount         |
|---------------------------|-----|-----------------------|----------------|
| <u>SPECIAL NETT ITEMS</u> |     |                       |                |
| 1                         | 1   | Rear box bracket      | K 120.00 X     |
| 2                         | 1   | Rear box              | nd/hg 280.00 ✓ |
| 3                         | 1   | Front number plate    | sm 30.00 X     |
| 4                         | 1   | Front sport rim       | h 220.00 Z     |
| 5                         | 1   | Front tyre            | sm 80.00 X     |
| 6                         | 1   | Steering cone bearing | sm 100.00 ✓    |
| 7                         | 1   | Wheel bearing         | sm 120.00 ✓    |
|                           |     |                       | 950.00         |

LABOUR & MISC CHARGES

|                                              |                                                                       |                   |
|----------------------------------------------|-----------------------------------------------------------------------|-------------------|
| 1                                            | To replace and realign all damaged portions                           | 450.00 180        |
| 2                                            | To replace and balance front rim                                      | ~ 150.00 20       |
| 4                                            | To knock and straighten chassis body                                  | nn 280.00 X       |
| 5                                            | To remove and refit front fork assy                                   | 180.00 80         |
| 6                                            | To supply spray paint material and necessary items on damaged portion | 330.00 200        |
| 7                                            | To reset and erase fault code                                         | nn 80.00 X        |
| <b>TOTAL</b>                                 |                                                                       | 1470.00           |
| <b>Total Parts and Labour Cost of Repair</b> |                                                                       | <b>\$7,821.71</b> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: