

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20008162/QPS3Q2

Date: 02/10/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : PC216P	Insured Vehicle No :	SHD3834A
Date of Loss: 30/07/2020	Nature of Claim: TP	Claim No: MCT20070413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC216P		
Make & Model:	GOLDEN DRAGON XML6957J14, 6.7 D (A)	Engine No:	ISBE422521972391
Reg. Date:	01/04/2011 (Man. Year: 2010)	Chassis No:	LL3BECDH9AA014494
Colour:	Multi-colour	Odometer:	8806 km
Engine Capacity:	6693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70R22.5	Rear Tyre Size:	275/70R22.5
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,408.48	5,509.58	7,898.90	58.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,370.00	3,660.00	4,710.00	56.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,778.48	9,169.58	12,608.90	57.90
Approved Total (Overridden) (S\$)		7,350.00		
Nett Amount (S\$)	21,778.48	7,350.00	14,428.48	66.25
+ Loss of Use (6.0 x S\$150.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,257.45		
Global Sum Settlement (S\$)		8,250.00		

INSPECTION

Date of Assignment:	06/08/2020	
Date Inspected:	07/08/2020	Inspected At: A T Auto Consultant (HQ) B/113 Teck Whye Lane, #05-650 Singapore 680113

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Sep 2020)	
Parts:	N/A	GOLDEN DRAGON XML6957J14 6.7 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC216P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	2,856.30 FL	*2,500.00 FL
2	1		*FRONT PANEL (NPA)	Repair	0.00 FL	*- FL
3	1		*FRONT DOOR GUARD RAIL LH	Dented	788.50 FL	*600.00 FL
4	1		*FRONT DOOR ASSY LH	Crumpled	3,965.10 FL	*2,000.00 FL
5	1		*SET FRONT DOOR WEATHERSTRIP	Cut	687.50 FL	*580.00 FL
6	1		*FRONT DOOR QUARTER GLASS	Scratched	386.20 FL	*386.20 FL
7	1		*FRONT DOOR FRAME PANEL (NPA)	Repair	0.00 FL	*- FL
8	1		*FRONT WHEEL PANEL	Repair	2,831.30 FL	*- FL
9	1		*COMPARTMENT DOOR WITH POCKET PANEL NOS 1 HANDLE /LOCK LH	Repair	1,283.50 FL	*- FL
10	1		*LUGGAGE DOOR NOS 1 LH (NPA)	Repair	0.00 FL	*- FL
11	1		*LUGGAGE DOOR NOS 2 LH (NPA)	Repair	0.00 FL	*- FL
12	1		*FRONT WHEEL RIM	Serviceable	1,200.00 FS	*- FS
13	1		*EXCURSION BUS STICKER	Necessary	50.00 FS	*50.00 FS
				Sub Total (\$\$)	14,048.40	6,116.20
				- List Item Discount on L Items 5.00/10.00% (\$\$)	639.92	606.62
				Total Parts (\$\$)	13,408.48	5,509.58

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING FOR REPLACE AND REPAIR AFFECTED PARTS	New	2,000.00	1,100.00
2	SPRAY PAINTING ON AFFECTED AREA FOR 3 COLOURS (8 PANELS)	New	3,200.00	2,000.00
3	APPLY PUTTY AND ANTI-CORROSION TO AFFECTED PARTS	New	1,600.00	100.00
4	R&R FRONT DOOR HANDLE/LOCK/MECHANISM /MOTOR	New	800.00	150.00
5	R&R LUGGAGE HANDLE /LOCK MECHANISM	New	450.00	50.00
6	R&R FRONT DOOR GLASS PANEL TO FACILITATE REPAIR	New	200.00	200.00
7	FRONT DOOR GLASS SEALANT	New	120.00	60.00
Gross Labour Cost (S\$)			8,370.00	3,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >