

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 20 Aug 2020

Preliminary AdviceInsured Vehicle No : GX4308C
TP Vehicle No : SMG3506Y
Make : HONDA CITY
Date of Inspection : 07/08/2020
Inspection At : STK AUTO (S) PTE LTD (HQ)
8 KAKI BUKIT AVE4, #03-21
SINGAPORE 415875Accident Date : 29/07/2020
Assignment Date : 06/08/2020
Est. Duration of Repair : 4**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,732.59
Revised Amount	:S\$	2,774.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,774.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :