

SS. REC. BY:

REF:

AIG / 200081701Kc

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Merlin

Veh No:

SFF 25 B

Yr Regn:

03, 14

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 520i

c.c.

1997

Colour:

M.D. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

167853

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBA5A320100334089

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

245/45ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

5/8/20

D.O.I.

11/8/2020

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Est not ready.

612m 831501 Confirmed

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐


: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



Not Authorised Estimates
L/Ry @ 3150h
4 days

Vehicle no. SFF25B
Make Model: BMW 520i
Owner: Phua Mei Fang

Kenneth
96910663

Date: 7 Aug 20
TP Insurer: AIG

S/N	Parts - Description	Qty/ Set	Unit Price	Amount S\$
1	Rear bumper 1571.95	1	CM 2,625.00	2,625.00 ✓
2	Rear bumper clips	1	45.00	45.00 ✓
3	Rear bumper reflector	1	84.00	84.00 X
4	Rear bumper reinforcement 691.75	1	1,007.50	1,007.50 ✓
5	Rear bumper retainer, upper 180	1	775.00	775.00 ✓
6	Rear bumper retainer, lower	1	165.00	165.00 ✓
7	Rear bumper retainer, side	1	260.00	260.00 X
8	Bootlid	1	2,835.00	2,835.00 X
9	Bootlid weatherstrip	1	240.00	240.00 X
10	Emblem, BMW logo 85.00	1	125.00	125.00 ✓
11	Emblem, "520i"	1	98.00	98.00 ✓
12	Rear bumper under cover	1	90.00	90.00 ✓
(1) Sub-total for parts:				8,259.50

108

S/N	Parts, S-Nett - Description	Qty/ Set	Unit Price	Amount S\$
1	Reverse sensors (set)	1	450.00	450.00 X
(2) Sub-total for s-nett parts:				450.00

S/N	Labour & Materials - Description	Amount S\$
1	Labour to remove/ refit/ renew/ replace affected parts	1,350.00 500
2	Spray painting	900.00 600
3	Check wiring harness and function of reverse sensor	80.00 20
4	Remove and install reverse sensor	60.00 ✓
5	Reset fault code	450.00 120
(3) Sub-total for Labour & Materials:		2,840.00

Grand Total (1+2+3): 11,549.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: