



NOT Authorised Estimates

L/Rup 83150h

4 days

Kenneth
98910663

Vehicle no. SFF25B
Make Model: BMW 520i
Owner: Phua Mei Fang

Date: 7 Aug 20
TP Insurer: AIG

S/N	Parts - Description	Qty/ Set	Unit Price	Amount S\$
1	Rear bumper 1571.95	1	CM 2,625.00	2,625.00 ✓
2	Rear bumper clips	1	45.00	M 45.00 ✓
3	Rear bumper reflector	1	84.00	R 84.00 X
4	Rear bumper reinforcement 691.75	1	1,007.50	R 1,007.50 ✓
5	Rear bumper retainer, upper 180	1	775.00	Dii 775.00 ✓
6	Rear bumper retainer, lower	1	165.00	CM 165.00 ✓
7	Rear bumper retainer, side	1	260.00	R 260.00 X
8	Bootlid	1	2,835.00	R 2,835.00 X
9	Bootlid weatherstrip	1	240.00	R 240.00 X
10	Emblem, BMW logo 85.00	1	125.00	M 125.00 ✓
11	Emblem, "520i"	1	98.00	M 98.00 ✓
12	Rear bumper under cover	1	90.00	CM 90.00 ✓

108

(1) Sub-total for parts: 8,259.50

S/N	Parts, S-Nett - Description	Qty/ Set	Unit Price	Amount S\$
1	Reverse sensors (set)	1	450.00	R 450.00 X

(2) Sub-total for s-nett parts: 450.00

S/N	Labour & Materials - Description	Amount S\$
1	Labour to remove/ refit/ renew/ replace affected parts	1,350.00 500h
2	Spray painting	900.00 600h
3	Check wiring harness and function of reverse sensor	80.00 20h
4	Remove and install reverse sensor	60.00 ✓
5	Reset fault code	450.00 120h

(3) Sub-total for Labour & Materials: 2,840.00

Grand Total (1+2+3): 11,549.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: