

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ms:China Taiping Insurance (Singapore) Pte Ltd

Date: 6/8/2020

Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLM3129H

CHASSIS NO: RU 31213095

MAKE / MODEL: Honda Vezel Hybrid 1.5X Auto

DATE OF ACCIDENT: 05/08/2020

YOUR INSURED VEHICLE NUMBER: SLR3327B

MILEAGE: 285975 Km

PARTS DESCRIPTION

- | | | |
|---|--------------------------------|------|
| 1 | Front bumper | X R |
| 2 | F/L fender | / pp |
| 3 | F/R fender wheel arch moulding | /scr |
| 4 | F/L headlamp assy (LED) | Xscr |

QTY	UNIT PRICE	LIST PRICE
1PC	\$ 955.00	\$ 955.00 ^x
1 PC	\$ 600.00	\$ 600.00 [/]
1PC	\$ 300.00	\$ 300.00 ¹⁹⁵
1PC	\$ 2,100.00	\$ 2,100.00 ^x
LIST TOTAL S\$:		\$ 3,955.00 ⁷⁹⁵
20.00% DISCOUNT S\$:		\$ 791.00 ^{20%}
		\$ 3,164.00 ⁶³⁶

SPECIAL NETT

- | | | |
|---|--------------|------|
| 1 | Bumper clips | Xscr |
|---|--------------|------|

1 SET	\$ 80.00 ⁴⁰⁰
Special Nett Total S\$:	\$ 80.00

LABOUR CHARGES

- | | | |
|---|---|--------------------------|
| 1 | To labour charge for removing front bumper and F/L fender out to facilitate repairs and replacement of damaged parts. | \$ 750.00 ⁴⁰⁰ |
| 2 | To respray front bumper, F/L fender wheel arch moulding and F/L fender | \$ 800.00 ⁵⁰⁰ |

LABOUR TOTAL S\$:	\$ 1,550.00 ⁹⁰⁰
TOTAL S\$:	\$ 4,794.00
7% GST	\$ 335.58
GRAND TOTAL S\$:	\$ 5,129.58

Repair dy - 3 days

2/5

Afterpaint photo

Sun Pin (Hdn)

07/08/2020

TP without prejudice.

P=636
L=900
1,536
- 20%
1,228.8
2/5
\$1,250

3 days