



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2205527

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 08/09/2022
Reference CC4/FCI20008173/Apa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBC 9107C
Insured Veh. SHC 7413K
Claim No. D20003064MFSH
Policy No. D-20094921MFSH
Accident Date 01/08/2020
Inspection Date 07/08/2020

Description	Total
Survey Inspection	219.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	219.00
GST (7%)	15.33
Grand Total	234.33

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20008173/Apa3q2	
			Date: 08/09/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7413K	Veh. Inspected	GBC 9107C	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20003064MFSH	Excess (\$)	0.00	
Assign From	ERIC WOO	Assign Date	07/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JN1MC2E26Z0001482	Colour	BLUE	
Odometer	84982 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/08/2020	Inspection Date	07/08/2020	
Survey held at	CHIN MENG MOTORS 1 KAKI BUKIT AVE 6 #01-40/63 SINGAPORE 417883.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 9107C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (N)	TO REPAIR SEE LABOUR	571.90	-
4	FRONT BUMPER SOCKET CLIP @\$5.00 (N)	NECESSARY	20.00	20.00
1	HEADLAMP (N)	CUT	441.90	441.90
	LESS 10% DISCOUNT		-103.38	-46.19
			930.42	415.71
<u>SPECIAL NETT ITEMS</u>				
1	FRONT R/H DOOR STICKER-CO REG (SN)	NECESSARY	20.00	20.00
			20.00	20.00
<u>LABOUR</u>				
	TO PANEL BEATING,WELDING,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE PARTS AS MENTIONED ABOVE ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		200.00	100.00
	TO RESPRAY AFFECTED PART.		500.00	400.00
	TO REMOVE & REFIT OF WIRINGS.		30.00	30.00
			730.00	530.00
GRAND TOTAL			1,680.42	965.71
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				750.00

Report Ref No. CC4/FCI20008173/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 9107C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBC 9107C

RE-INSPECTION

