

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST186/20/CIS

Your Ref: To be advised

6-Aug-20

MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Nissan NV350 no: GBC9107C

Date of accident: 01-08-2020

Parts supply (Nett):

- 1 pc Front bumper *Reps*
4 pcs Front bumper socket clip @\$5.00 *Reps*
1 pc Headlamp *Reps*

461.90	571.90
415.71	20.00 ✓
	441.90 ✓
	461.90
Less 10%:	(46.19)
	20.00 ✓
	435.71

S/Nett Items

- 1 pc Front R/h door sticker - Co reg (S/Nett) *Reps*

Labour charges:

- To panel beating, welding, removing damaged parts and replacement of the parts as mentioned above etc.
To respray affected part.
To remove & refit of wirings.

530	200.00 ✓
	500.00 ✓
	30.00 ✓
SS	1,165.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lj
2/s 07/08/20
02Rj
total: 945.71
h/s: 750