



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number 63685592	
Estimator Telephone Number 68662623	
Accident Reporting Number 68662672	

Date Generated : 07/08/2020

User ID : GohKK2

Section A - Accident Details

Registration Number	SG1184J
Case Reference Number	BUS/08/20/1004
Registration Date	14/11/2016
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Kah Siew Hwee
Type of Accident	Side Swipe
Accident Date and Time	4/8/2020 5:56 AM
Accident Reported Date and Time	4/8/2020 6:45 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SG1184J-RIGHT REAR PORTION SHD6774J COMFORT DELGRO TAXI (TP) INSURED WITH III
Prepared Date and Time	6/8/2020 11:46 AM
Chassis Number	WEB62808323130019
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$5,500.12	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$5,500.12	\$0.00
Lump Sum Total	\$7,700.00	\$0.00
Number of Repair Days	4.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	06/08/2020 11:51 AM	
Signature		✖
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757706
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 07/08/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,590.00	795
Total Labour	\$1,590.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$602.00	510.
Total Spray Painting & Panel Beating	\$602.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009909	BODY RH		BUMPER, REAR, RH, FOR MB CITARO O530	1.00	\$837.84	10.00	\$754.06	Replace	X R
6009879	VE	0008206864	LAMP, TAIL, REAR LH, FOR MB CITARO O530	1.00	\$1,261.71	10.00	\$1,135.54	Replace	X SVC
6010012	VE	0005446911	LAMP, SIDE MARKER, FOR MB CITARO O530 BUS	1.00	\$94.50	10.00	\$85.05	Replace	X SVC
6010141	ENGINE	6287503206	FLAP, RADIATOR, FOR MB CITARO O530	1.00	\$5,445.00	10.00	\$4,900.50	Replace	X R.
Total					\$7,639.05		\$6,875.15		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair pay - 3 days

L/S

After paint photo

Sun Pin (LKK)

07/08/2020

TP with prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: