



HKL LIM
TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklmteammotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292
Website: www.hklmteammotorsport.com.sg

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \$150 ✓
Date: \$980 ✓

FX1061U

1	LAMP STAY <i>?bt/</i>		
2	METER ASSY <i>?cm/</i>		
3	FRONT FORK ASSY <i>bt/</i>	\$900 ✓	
4	FRONT FORK UNDER BRACKET <i>?bt/</i>	\$480 ✓	
5	STEERING CONE BEARING <i>nee/</i>	\$120 ✓	
6	FRONT FORK TOP CAM <i>?bt/</i>	\$220 ✓	
7	BODY FRAME ALIGNMENT <i>repair</i>	\$680 300L *	
8	FRONT FENDER <i>bo/</i>	\$180 ✓	
9	FRONT WHEEL RIM <i>scr/</i>	\$750 ✓	
10	FRONT WHEEL SHALF <i>scr/</i>	\$120 ✓	
11	FRONT WHEEL BEARING 2PCS <i>nee/</i>	\$40 ✓	
12	FRONT WHEEL BEARING OIL SEAL <i>nee/</i>	\$30 ✓	
13	FRONT BRAKE DISC LH/RH <i>?bt/</i>	\$940 ✓	9080
14	HEAD COWLNG <i>cm/</i>	\$220 ✓	
15	STATER SWITCH LH/RH <i>x sn</i>	\$480 ✓	10%
16	FRONT SIGNALS <i>x sn</i>	\$60 ✓	8172
17	IU UNIT <i>x sn</i>	\$170 ✓	
18	IN UNIT BRACKET <i>x sn</i>	\$35 ✓	
19	HANDLE BAR (DIMOTIV CARBON) <i>bt/</i>	\$380 ✓	
20	HANDLE BAR GRIP <i>x sn</i>	\$25 ✓	
21	HANDLE BAR MIRROR <i>bo/</i>	\$150 ✓	
22	BRAKE LEVER + CLUTCH LEVER (BREMBO) <i>scr/</i>	\$140 ✓	
23	HEADLIGHT <i>?cm/</i>	\$320 ✓	8172
24	HEADLIGHT BRACKET LH/RH <i>?bt/</i>	\$180 ✓	1100
25	FRONT BRAKE PUMP <i>scr/</i>	\$320 ✓	30
26	ENGINE GUARD <i>scr/</i>	\$120 ✓	9302
27	ENGINE GUARD CLOTH <i>turn/</i>	\$50 ✓	20%
28	LEWER COWLING <i>scr/</i>	\$120 ✓	7441.60
29	RADIATOR <i>x nn</i>	\$650 ✓	43-7,400
30	COOLANT WATER <i>x nn</i>	\$55 ✓	
31	FRONT FOOT REST BRACKET RH <i>x sn</i>	\$250 ✓	
32	FUEL TANK <i>bt/</i>	\$890 ✓	
33	EXHAUST HEADER + GASKET <i>scr/ x nn</i>	\$780 ✓	
34	EXHAUST MUFFLER (YOSHIMURA) <i>bt/</i>	\$950 ✓	
35	EXHAUST GUARD RH <i>scr/</i>	\$90 ✓	
36	EXHAUST INSPECTION <i>nee/</i>	\$90 ✓	
37	SPRAY PAINTING	\$580 300 450 *	
38	THROTTLE CABLE <i>cut/</i>	\$150 ✓	
39	TOWING	\$30 ✓ receipt?	
40	LABOUR	\$780 350 *	

TOTAL AMOUNT:

Repair limit
\$5,200

\$13,655 * Labour - 1100

Towing - 30

Resul
Hp 900w068
5 days
4/8
07/08/2020
@ 1600
Resurvey
after
repair