

IFORTDELGRO ENGINEERING PTE LTD  
AIR ESTIMATE\*

LKK/Chang,  
06/08/2020

VEHICLE NO SHD3027M  
MAKE :  
MODEL I-40

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOT LID			\$2,174.90
1	BOOT HINGE /RH			\$142.30
1	BOOT LID H EMBLEM			\$28.70
1	BOOT LID CRDI PLATE			\$27.90
1	BOOT LID I 40			\$27.90
1	BOOT LID LAMP /RH			\$565.60
1	TAIL LAMP /RH			\$697.80
1	REAR BUMPER			\$1,106.00
	<b>SUB TOTAL</b>		3522.80	<b>\$4,771.10</b>
	<b>20.00%</b>			\$954.40
			20% - 2818.24	<b>\$3,817.60</b>
1	REAR NUMBER PLATE			\$55.00
1	BOOTLID COMFORT LOGO STICKER			\$30.00
1	BOOTLD COMFORT TEL NO. STICKER			\$30.00
			60	<b>\$115.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$540.00
	Spray Painting Charge			\$640.00
	Towing Fee			\$60.00
	Tuff Kote		1140	\$90.00
	Check Lighting			\$60.00
	<b>TOTAL LABOUR</b>		4018.24	<b>\$1,390.00</b>
	<b>ESTIMATE TOTAL</b>		4583.200 02 days	<b>\$5,322.60</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanf... 97475749  
WP' 7/8/2004  
... 02-03 days  
... after repair  
Tanf...  
Hendrick

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: