

SMD8050C

Honda Freed

GB71072488

TP MSIG

Dense

Front Number Plate	Dented	30(SN) ✓
Front Number Plate Holder	Deformed	30(SN) ✓
Front Bumper	Deformed	950.80 ✓
Front Bumper Clips	N/A	30 ✓
Front Bumper Side Holder x 02	N/A	55x2 = 110 ✓
Front Bumper Reinforcement	Dented	295.80 ✓
Front Bumper Tow Cover	N/A	25.60 +
Front Bumper Lower Grille	Deformed	146.50 ✓
Front Bumper Lower Grille Side Garnish x 02	N/A	45.8x2 = 91.60 X
Front Grille Assy	Cracked	740.20 ✓
Front Grille Clips	N/A	20 ✓
Headlamp x 02	LH cracked	1980.2 = 3960.4
Headlamp Lower Bracket x 02	LH cracked	38.5x2 = 77 38.50
Bonnet	{ N/A N/A	720.60 X
Bonnet Lock		103.70 X

SMD8050C

Air Con Condenser	2 14 m	985.10	x
Radiator		987.90	x
Front Support Panel		752.60	x

Panel Beating	800.	350
Spray Painting	700	250
Wiring	50	30

To remove condenser and top up air con gas 120 x

To remove radiator and top up coolant. 120. x

Wst 4311.50 Labor 630

Len 20% 3449.20 Total 4139.20

S.N: 60

1/81 3.3K

04 Days

11 917.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: