

Vehicle No: **SKG 4215 D**
Report No: **TP/ 04-19011/DY / 2019**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Sub Total c/f	\$ 39885.74	\$ 36107.05
12	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 380.00	\$ 210.00
13	To remove, refit and reset roof top air bag system.	\$ 1800.00	\$ 1200.00
	Total	\$ 42065.74	\$ 37517.05

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 30000.00

SDLS: THIRTY THOUSAND ONLY



Qualified Appraiser





























