



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD20005214/Eyf3e2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 18-08-2020



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJN 6351E	Veh. Inspected	SKH 8154P
Policy No.	PNPV2018-00002319-02	Coverage (\$)	0.00
Claim No.	1202000016027	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	07/08/2020

2. Vehicle Particulars & Condition

Make & Model	BMW 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	WBA3A12050J719524	Colour	RED
Odometer	121608	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	PIRELLI	5 mm
L/H Front Tyre	225/50 R17	PIRELLI	5 mm
R/H Rear Tyre	225/50 R17	PIRELLI	5 mm
L/H Rear Tyre	225/50 R17	PIRELLI	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/04/2020	Inspection Date	16/04/2020
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------