

ASS. REC. BY:

REF:

1416/20008198/Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/19/21 Pm @ 2900h - Confirmed

Data/Time, File Pass 10?

☐

Preil. Report

1)

Data/Time, File Return 10?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Veh No:

SUC 5074X

Yr Regn:

05, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c.

1496

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

213453

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

Ru3

1132455

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: CST 215/60R16

R: 7.5R12P

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

5/8/20

D.O.I.

2/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



ESTIMATE

Date :	29/08/2020	Reg No :	SLC5074X
To :	AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model :	HONDA VEZEL HYBRID
Attn. :		Chassis No :	RU31132455
Office / Mobile :		Engine No :	LEB5082480
Email Address :		Quotation No. :	116517
		Ref. No. :	
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	05/08/2020
Attn. :	KONYINSIEW	Policy No. :	5111416799-01-000006
Office / Mobile :	+65 6861 0007	Claim Type :	TP CLAIM - AIG
Email / Fax No. :	KonYinSiew@goldbell.com.sg	Workshop :	8 TUAS AVE 18

Not Authorized
11 Pump & Assembly After Paint
4 days

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		REAR WINDSCREEN MOULDING	1	165.00	-20	132.00	132.00 ✓
2		TAILGATE <i>1108.00</i>	1	2,458.00	-20	1,966.40	1,966.40 ✓
3		TAILGATE WEATHERSHIP	1	215.00	-20	172.00	172.00 ✓
4		TAILGATE HINGE LH	1	123.00	-20	98.40	98.40 X
5		TAILGATE HINGE RH	1	123.00	-20	98.40	98.40 X
6		TAILGATE STAY ASSY LH	1	248.00	-20	198.40	198.40 X
7		TAILGATE STAY ASSY RH	1	248.00	-20	198.40	198.40 X
8		TAILGATE EMBLEM - HONDA	1	98.00	-20	78.40	78.40 X
9		TAILGATE LOGO - VEZEL	1	73.00	-20	58.40	58.40 ✓
10		TAILGATE LOGO - HYBRID	1	77.00	-20	61.60	61.60 ✓
11		REAR BUMPER	1	812.00	-20	649.60	649.60 ✓
12		REAR BUMPER RETAINER LH	1	35.00	-20	28.00	28.00 X
13		REAR BUMPER RETAINER RH	1	35.00	-20	28.00	28.00 X
14		REAR REINFORCEMENT	1	316.00	-20	252.80	252.80 X
PARTS TOTAL :						4,020.80	

SPECIAL NETT ITEMS

1	TAILGATE CLIPS (SET)	1	30.00 ✓
2	REAR BUMPER CLIPS (SET)	1	30.00 ✓
3	REAR REVERSE SENSOR	1	300.00
4	REAR VEHICLE NUMBER PLATE	1	50.00 X
PARTS TOTAL:			410.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Date	: 29/08/2020	Reg No	: SLC5074X
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: HONDA VEZEL HYBRID
Attn.	:	Chassis No	: RU31132455
Office / Mobile	:	Engine No	: LEB5082480
Email Address	:	Quotation No.	: 116517
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 05/08/2020
Attn.	: KONYINSIEW	Policy No.	: 5111416799-01-000006
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIM - AIG
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	1800.00
2	TO REMOVE AND REFIX REAR WINDSCREEN	200.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	100.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRING	150.00
5	TO CONDUCT DIAGNOSTICS TEST AND RESET THE WARNING LIGHT	100.00 X
6	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1050.00

LABOUR TOTAL :	3,400.00
SUB-TOTAL :	7,830.80
GST @ 7% for \$ 7,830.80	548.16
GRAND TOTAL (\$\$) :	8,378.96

ESTIMATE

Date	: 29/08/2020	Reg No	: SLC5074X
To	: AIG ASIA PACIFIC INSURANCE PTE. LTD.	Model	: HONDA VEZEL HYBRID
Attn.	:	Chassis No	: RU31132455
Office / Mobile	:	Engine No	: LEB5082480
Email Address	:	Quotation No.	: 116517
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 05/08/2020
Attn.	: KONYINSIEW	Policy No.	: 5111416799-01-000006
Office / Mobile	: +65 6861 0007	Claim Type	: TP CLAIM - AIG
Email / Fax No.	: KonYinSiew@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

PREPARED BY : KONYINSIEW

DATE / TIME : 21/9/20

SURVEYOR : Kenneth

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____