



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2105699

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 13/08/2021
Reference CC4/CTI20008199/Ues3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. PA 9704Z
Insured Veh. PD 108M
Claim No. SNM20D202805
Policy No. DMB1SN3069361900
Accident Date 07/08/2020
Inspection Date 07/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC4/CTI20008199/Ues3q2 Date: 13/08/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PD 108M	Veh. Inspected	PA 9704Z	
Policy No.	DMB1SN3069361900	Coverage (\$)	0.00	
Claim No.	SNM20D202805	Excess (\$)	0.00	
Assign From		Assign Date	07/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	KING LONG XMQ6117K	c.c	6693	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	LA6R1FSH39B102796	Colour	WHITE / RED	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	TAITONG	6 mm	
L/H Front Tyre	11 R22.5	TAITONG	6 mm	
R/H Rear Tyre	11 R22.5 (D)	TAITONG	6/6 mm	
L/H Rear Tyre	11 R22.5 (D)	TAITONG	6/6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	07/08/2020	Inspection Date	07/08/2020	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		13 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PA 9704Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR ENGINE HOOD	DISTORTED	6,500.00	3,280.00
1	REAR ENGINE HOOD OUTER HANDLE	NOT NECESSARY	485.00	-
1	REAR ENGINE HOOD SIDE LOCK O/S	TWISTED	90.00	90.00
1	REAR ENGINE HOOD DAMPER ASSY O/S	SERVICEABLE	350.00	-
1	REAR TAILLAMP O/S	BROKEN	1,250.00	825.00
1	REAR TAILLAMP PANEL O/S	CRACKED / DISTORTED	3,850.00	1,500.00
1	REAR BODY PANEL O/S	CRACKED / DISTORTED	6,800.00	3,300.00
2	REAR BODY COMARTMENT PANEL O/S	DISTORTED	3,900.00	3,900.00
1	REAR BODY COMARTMENT PANEL INNER BRACKET O/S	BENT	1,100.00	680.00
1	REAR BODY COMARTMENT PANEL INNER ALUMINIUM PLATE O/S	DISTORTED / BUCKLED	2,200.00	1,600.00
1	REAR WHEEL MUDGUARD PANEL O/S	BENT / BUCKLED	4,900.00	2,900.00
1	REAR WHEEL MUDGUARD PANEL INNER BRACKET O/S	TO REPAIR SEE LABOUR	850.00	-
1	REAR WHEEL MUDGUARD PANEL INNER ALUMINIUM PLATE O/S	DENTED / BUCKLED	2,800.00	1,600.00
1	REAR BUMPER	DISTORTED	3,500.00	2,200.00
1	REAR BUMPER REFLECTOR O/S	BROKEN	50.00	50.00
1	REAR BUMPER BEAM	BENT	1,850.00	1,520.00
1	RADIATOR	BENT / PUNCTURE	3,650.00	2,815.00
1	RADIATOR FAN BLADE	BROKEN	399.00	399.00
1	RADIATOR FAN CLUTCH ASSY W/PULLEY	JAMMED / TWISTED	2,400.00	1,600.00
1	RADIATOR FAN TENSIONER PULLEY ADJUSTER	TWISTED	485.00	360.00
1	RADIATOR FAN BELT	SERVICEABLE	205.00	-
1	RADIATOR FAN COWLING	CRACKED	969.00	969.00
1	RADIATOR EXPANSION TANK	SERVICEABLE	850.00	-
1	RADIATOR FAN CLUTCH ASSY LOWER BRACKET	BENT	2,100.00	1,500.00
1	RADIATOR HOSE PIPE	TWISTED	250.00	215.00
2	ENGINE MOUTNINGS @\$350.00	O/S TORN	700.00	350.00
1	REAR ENGINE HOOD TOP PANEL	TO REPAIR SEE LABOUR	8,000.00	-

Report Ref No. CC4/CTI20008199/Ues3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BODY COMPARTMENT PANEL LAMP O/S	BROKEN	95.00	95.00
	LESS 10% DISCOUNT		-	-3,174.80
			60,578.00	28,573.20
	<u>SPECIAL NETT ITEMS</u>			
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	20.00	-
1	SET REAR ENGINE HOOD CORPORATE STICKER (SN)	NECESSARY	600.00	300.00
1	REAR 60KM/H STICKER (SN)	NECESSARY	20.00	10.00
			640.00	310.00
	<u>LABOUR</u>			
	TO REMOVE & REFIX INTERIOR FILLING TO ENABLE BODY WORK REPAIR .		500.00	200.00
	TO RUST PROOF THE AFFECTED PORTION.		150.00	50.00
	TO REMOVE & REFIX REAR WINDSCREEN .	NOT NECESSARY	450.00	-
	TO RESTART ENGINE & PERFORM ENGINE DIAGNOSIS TEST.	NOT NECESSARY	500.00	-
	TO REMOVE & REPLACED ENGINE MOUNTING .		80.00	50.00
	TO BEATING ,CUT ,WELD STRAIGHTEN & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR WHEEL MUDGUARD PANEL INNER BRACKET O/S AND REAR ENGINE HOOD TOP PANEL .		5,000.00	3,000.00
	TO PUTTY & SPRAY PAINTING.		3,000.00	1,500.00
	TO CHECK WIRING .		150.00	30.00
			9,830.00	4,830.00
GRAND TOTAL			71,048.00	33,713.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				25,000.00

Report Ref No. CC4/CTI20008199/Ues3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 9704Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 9704Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PA 9704Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

