

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

LKK Asher

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

not Authorized
1/5 @ 25,000/
13 days.

VEHICLE No: PA 9704Z

1PC	REAR ENGINE HOOD	3280.00	DIS	\$6,500.00	✓
1PC	REAR ENGINE HOOD OUTER HANDLE		11	\$485.00	X
1PC	REAR ENGINE HOOD SIDE LOCK O/S		Tw	\$90.00	✓
1PC	REAR ENGINE HOOD DAMPER STAY O/S		SCC	\$350.00	X
1PC	REAR TAILLAMP O/S	825.00	SW	\$1,250.00	✓
1PC	REAR TAILLAMP PANEL O/S	1500.00	CR/DIS	\$3,850.00	✓
1PC	REAR BODY PANEL O/S	3300.00	CR/DIS	\$6,800.00	✓
2PCS	REAR BODY COMPARTMENT PANEL O/S		DIS	\$3,900.00	✓
1PC	REAR BODY COMPARTMENT PANEL INNER BRACKET O/S	680.00	Self	\$1,100.00	✓
1PC	REAR BODY COMPARTMENT PANEL INNER ALUMINIUM PLATE O/S		DIS/SCC	\$2,200.00	✓ 1600
1PC	REAR WHEEL MUDGUARD PANEL O/S	2900	Self/SCC	\$4,900.00	✓
1PC	REAR WHEEL MUDGUARD PANEL INNER BRACKET O/S		R	\$850.00	X
1PC	REAR WHHEL MUDGUARD PANEL INNER ALUMINIUM PLATE O/S	1600	DIS/SCC	\$2,800.00	✓
1PC	REAR BUMPER	2200	DIS	\$3,500.00	✓
1PC	REAR BUMPER REFLECTOR O/S		SW	\$50	✓
1PC	REAR BUMPER BEAM	1520	Self	\$1,850.00	✓
1PC	RADIATOR	2815	Self/PAH	\$3,650.00	✓
1PC	RADIATOR FAN BLADE		SW	\$399.00	✓
1PC	RADIATOR FAN CLUTCH ASSY W/PULLEY	1600.00	Tw/Tw	\$2,400.00	✓
1PC	RADIATOR FAN TENSIONER PULLEY ADJUSTER	360.00	Tw	\$485.00	✓
1PC	RADIATOR FAN BELT		SCC	\$205.00	X
1PC	RADIATOR FAN COWLING		CR	\$969.00	✓
1PC	RADIATOR EXPANSION TANK		SCC	\$850.00	X
1PC	RADIATOR FAN CLUTCH ASSY LOWER BRACKET	1500.00	Self	\$2,100.00	✓
1PC	RADIATOR HOSE PIPE	215.00	Tw	\$250.00	✓
2PCS	ENGINE MOUNTINGS @\$350.00		0/15 torn	\$700.00	✓
1PC	REAR ENGINE HOOD TOP PANEL		R	\$8,000.00	X
1PC	REAR BODY COMPARTMENT PANEL LAMP O/S		SW	\$95.00	✓
				\$60,578.00	

(102)

S.NETT

1PC	REAR LICENCE PLATE	11	\$20.00	X
1SET	REAR ENGINE HOOD CORPORATE STICKER	ME	\$600.00	300
1PC	REAR 60KM/H STICKER	ME	\$20.00	10

TO CHECK WIRING	\$150.00	30
TO REMOVE & REFIX INTERIOR FILLING TO ENABLE BODY WORK REPAIR	\$500.00	200
TO RUST PROOF THE AFFECTED PORTION	\$150.00	50
TO REMOVE & REFIX REAR WINDSCREEN	\$450.00	X
TO RESTART ENGINE & PERFORM ENGINE DIAGNOSIS TEST	\$500.00	X
TO REMOVE & REPLACED ENGINE MOUNTING	\$80.00	50
TO BEATING CUT, WELD STRAIGHTEN & REPLACED PARTS	\$5,000.00	3000

31748

37713
214970

TO PUTTY & SPRAY PAINTING

TOTAL \$3,000.00 / 500
\$71,048.00