

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte Ltd
AIG Building Level 1
78 Shenton Way
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT

DEAR SIR / MADAM :

ACCIDENT REPAIR ON: SKF5768Z
MODEL : TOYOTA COROLLA ALTIS
POLICY NO :D20MTPV01007155
CHASSIS NO : MR053ZEE104132669

DATE / TIME OF ACCIDENT: 5/08/2020 Time: 0715Hrs at Lot 17 Carpark Blk 205 Bishan St 23
THIRD PARTY VEHICLE NO: SJC1166P

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Parts Type	Quantity	Unit Price S\$	Condition	Amount S\$
1	Front bumper	Bu	437.00		437.00
2	Front bumper clip	nu	5.50		5.50
3	Front bumper retainer L	su	55.00		55.00
4	Front bumper retainer R	Di	55.00		55.00
5	Front bonnet	R	901.00		901.00
6	Front fender	n	610.00		610.00
7	Front fender guard	su	165.00		165.00
8	Front fender guard clip	nn	5.50		5.50
9	Front headlight R	su	713.00		713.00
10	Front support panel	R	721.00		721.00
11	Front bumper fog lamp cover R	su	85.00		85.00
12	Head lamp assy R	su	450.00		450.00
13	Head lamp lower bracket R	NA	NA		NA
14	Front bumper reinforcement	R	345.00		345.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour Charges For Rear Portion

- 1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts. (Front)
- 2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities (Front)
- 3 Provide skill labour to disconnect and check electrical wiring
- 4 Provide skill labour to wheel alignment
- 5 Provide skill labour for undercarriage (Front)

Total Labour:

25 Sub-Total: 4,548.00
Less: 5% discount - 227.40
Total Parts after 5% discount: 4,320.60

Total Parts: 4,320.60

Total Parts & Labour: 3,080.00
GST 7% 7,400.60
Grand Total: 518.04
7,918.64

Estimate Repair Duration

05 days