

**1st Autoworks Pte Ltd**  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

**Repair Estimate**

Reference: SMR8098S  
B.M.W. / 216I  
GRAN TOURER  
HALOGEN  
LIGHT  
Make:

Date : 6/8/2020

TP A161  
Jia Le

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SMR8098S  
CHASSIS NO.: WBA6V120105P77446  
ENGINE NO.: 40285882B38A15A

Name of insured : Alpine Car Rental Pte Ltd  
Date of accident.: 05/08/2020

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts		Part Description	Price (SGD)
1	1	BONNET <i>Dented</i>	\$ 1,321.90 ✓
2	10	BONNET INSULATOR CLIP <i>new</i>	\$ 68.00 +
3	1	LHF FENDER <i>Dented</i>	\$ 725.30 ✓
4	5	LHF FENDER LINER CLIP <i>new</i>	\$ 34.00 r
5	1	LHF FENDER QUARTER GLASS <i>new</i>	\$ 289.36 +
6	1	WITH MOULDING	\$ 1,580.60 ✓
7	1	LHF HEADLAMP <i>new</i>	\$ 1,298.30 x
8	1	FRONT BUMPER <i>Repair</i>	\$ 68.00 x
9	10	FRONT BUMPER CLIP <i>new</i>	\$ 120.70 +
10	1	BMW FRONT BUMPER LOGO <i>new</i>	\$ 71.90 ✓
11	1	LHF FENDER INNER MOULDING <i>cracked</i>	\$ 89.80 /
12	1	LHF FENDER INNER BRACKET <i>Bent</i>	\$ 58.10 +
13	1	LHF BUMPER BRACKET <i>new</i>	\$ 198.40 +
14	1	LHF HEADLAMP LOWER BRACKET <i>new</i>	\$ 198.40 +

3789.50

3410.55

Parts Total: \$ 5,924.36  
Less 10%: \$ 592.44  
Total : \$ 5,331.92

**Labour**

**Labour Description**

**Price (SGD)**

**No.**

**Front portion**

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 800.00	500
2	Carry out spray painting on accident affected area	\$ 1,000.00	750
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	S.R.S. Reset of system	\$ 300.00	+
5	To refocus headlamp	\$ 80.00	+

1280

Labour Total : \$ 2,210.00

### Others

### Other Description

No. Qty

Price (SGD)

### Front portion

	N.A.	
--	------	--

Other Total: \$ -

Total: \$ 7,541.92  
GST 7%: \$ 527.93  
GRAND TOTAL: \$ 8,069.86

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully,

Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

Adrian Lj

total: 4690.55

P/P 07/08/20

(P/P)

04 Days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

Asian Finishing

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd

78 SHENTON WAY

#07-16

SINGAPORE 079120

GST Ref. No: 20-0000274-Z

Vehicle No: SMR8098S

Invoice No:

Chasis No : WBA6V120105P77446

Invoice Date:

Engine No: 40285882B38A15A

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	BONNET	\$ 1,321.90
2	1	LHF FENDER	\$ 725.30
3	1	LHF HEADLAMP	\$ 1,580.60
4	1	MOULDING	\$ 71.90
5	1	LHF FENDER INNER BRACKET	\$ 89.80

Total: \$ 3,789.50

Less 10%: \$ 378.95

Parts Total : \$ 3,410.55

Labour

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 500.00
2	Carry out spray painting on accident affected area	\$ 750.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00

Labour Total : \$ 1,280.00

Other


No.	Other Description	Price (SGD)
	Front portion	
	N.A.	

Other Total : \$ -

Total : \$ 4,690.55

GST (7%) \$ 328.34

**Grand Total: \$ 5,018.89**

Yours Faithfully,  **Suhaimi Ong**

Suhaimi Ong

Service Advisor

Tel: 68441985 Fax:68445185

**E & O E**

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

**Please check and finalize with me this invoice**