LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Irene Tay Hui Ping Date: 14 Aug 2020

Preliminary Advice

Insured Vehicle No : GBJ7879J

TP Vehicle No : SFU1031Y Accident Date : 06/08/2020 : HONDA AIRWAVE : 07/08/2020 Make **Assignment Date**

: 13/08/2020 Est. Duration of Repair Date of Inspection : 4

Inspection At : AH LIM MOTOR COMPANY (AMK)

10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

The vehicle sustained impact / damages N/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,386.40
Revised Amount	:S\$	1,490.00
Check Items (Estimated)	:S\$	240.00
Total	:S\$	1,730.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: SURVEY ON WP (X)