

勝企業

Win Auto Enterprise

Blk 1033 Eunos Ave 5A #01-31

Singapore 409703

HP No: +65 9745 8981

Fax No: +65 6842 5778

TPEQ.
Shirley.

MR053HY9305048201

A. 8. 2020.

Estimated Quotation Vehicle No: SJC493B

Quantity	Items	Amount SGD\$
1 Pc	Rear Boot Lid <i>Distorted</i>	\$698.00 ✓ 665.90
1 Pc	Rear Boot Lid Lock <i>Dist</i>	\$138.00 ✓
1 Pc	Rear Boot Lid Center Garnish <i>Del</i>	\$288.00 ✓
1 Pc	Vios Logo <i>Nec</i>	\$48.10 ✓
1Pc	Rear Boot Lid Number Plate Lamp <i>not</i>	\$95.50 +
2Pcs	Rear Boot Lid Hing <i>LH Best</i>	\$500.00 (250) 685.00
1Pc	Rear Boot Lid Rubber <i>wt</i>	\$189.10 ✓
1Pc	Rear Boot Lid Center Logo <i>Nec</i>	\$55.10 ✓
1Pc	Rear Boot Lid J Logo <i>Nec</i>	\$39.50 ✓
1Pc	Rear Fender Left Side <i>Distorted</i>	\$659.00 ✓
1Pc	Rear Fender Under Shield <i>Nec</i>	\$298.00 +
1Pc	Rear Fender Under Air Take <i>Del</i>	\$198.10 65
4Pcs	Rear Fender Under Shield Clip <i>Nec</i>	\$19.20 +
1Pc	Rear Fender Inner Carpet <i>coupled</i>	\$198.30 ✓
8Pcs	Rear Fender Inner Carpet Clip <i>Nec</i>	\$50.40 30
1Pc	Rear Tail Lamp Panel <i>Distorted</i>	\$798.00 138
1Pc	Rear Tail Lamp Panel Garnish <i>coupled</i>	\$178.00 ✓
1Pc	Rear Tail Lamp Panel Lock <i>Nec</i>	\$123.10 +
2Pcs	Rear Tail Lamp <i>LH 298.60 X 2 3mold RH 60</i>	\$597.20 ✓
1Pc	Rear Bumper <i>Distorted</i>	\$468.00 ✓
1Pc	Rear Bumper Side Bracket <i>Nec</i>	\$79.30 ✓
1Pc	Rear Bumper Lower Reflector <i>Nec</i>	\$398.00 +

勝企業

Win Auto Enterprise

Blk 1033 Eunos Ave 5A #01-31

Singapore 409703

HP No: +65 9745 8981

Fax No: +65 6842 5778

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Set	Reverse Sensor	<i>Payd</i>	\$268.00	<i>200</i>
1Pc	Rear Tyre Cardboard	<i>for</i>	\$181.10	<i>✓</i>
1Pc	Rear Shock Absorber	<i>for</i>	\$358.00	<i>+</i>
1Pc	Rear Door Lock	<i>for</i>	\$422.00	<i>+</i>
1Pc	Rear Windscreen	<i>cut</i>	\$1,198.00	<i>✓ 1080</i>
1 Set	Windscreen Gum	<i>for</i>	\$49.00	<i>✓</i>
1 Set	Rear Windscreen Inner Shield	<i>for</i>	\$198.10	<i>✓</i>
	Total Amount		\$8,749.10	

561320

4208.90

Labour Charges	Amount SGD\$
To Remove and Fix Cushion	\$150 <i>80</i>
To Remove and Fix Windscreen	\$150 <i>120</i>
Towing Fee	\$80 <i>50</i>
To Check Wiring	\$80 <i>30</i>
To Spray Painting	\$1,200 <i>1100</i>
To Knocking and Welding	\$1,200 <i>1100</i>
To Spray Undercoating	\$180 <i>80</i>
To Remove and Fix Reverse Sensor	\$80 <i>50</i>
To Remove and Fix Rear Undercarriage	\$180 <i>X</i>
To Remove and Fix Petrol Tank	\$180 <i>80</i>
Total Amount	\$3,480

2690.

TOTAL \$12,229.10

Adrian C
h/s 11/08/20.
10 Days
total: 6899.50
h/s: SSK.

SSK