

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0525/2020/NS

26-Aug-20

Glory Tan

1 OF 1

SMF 9994 L

Audi Q5 2.0 TFSI qu

Quantity	Description	Unit Price	Amount
Labours			
1	To repair lhs rear fender.	\$ 800.00	250
2	To respray lhs rear fender.	\$ 1,000.00	550
TOTAL		\$ 1,800.00	

For Premium Automobiles Pte Ltd

Adrian Ling

27/08/20

SLG

Add 1 day

Authorised Signature

Car-in 26/8/2020 Kiam/Hong
wip: 43315

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

3 days

Material List for Accident Vehicle Regn No. SMF 9994 L

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR - LH <i>Dented</i>	\$ 3,118.00	✓
2	REAR DOOR SEAL BRACKET ?	\$ 42.00	?
3	REAR DOOR OUTER SEAL <i>new</i>	NEC \$ 203.00	✓
4	BONDING AGENT ?	NEC \$ 47.00	?
5	CLEANING SOLUTION ?	NEC \$ 65.00	?
6	SEALING STRIP <i>new</i>	\$ 16.00	x
7	REAR DOOR OUTER SEAL - LH REAR <i>new new</i>	\$ 220.00	✓ <i>SS</i>
8	REAR DOOR CATCH <i>new Dented</i>	\$ 144.00	✓ <i>SS</i>
9	REAR DOOR COVER - LH <i>new</i>	\$ 682.00	✓
10	REAR WHEEL COVER - LH <i>at</i>	\$ 577.00	✓
11	REAR ALUMINIUM RIM - LH <i>new</i>	\$ 1,091.00	+
12	WHEEL HOUSING LINER - LH <i>new</i>	\$ 275.00	+
13	SUNDRIES ?	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		: \$ 6,680.00	
TOTAL LABOUR CHARGES		: \$ 3,952.00	
GRAND TOTAL		: <u>\$10,632.00</u>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Add

8ko 837 199 x 6

special

3co 853 586 x 6

For LQ

