



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

11/08/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 05/08/2020

Supplementary repair cost for vehicle no: SGS8822J HONDA SHUTTLE HYBRID 1.5A 1

CHASSIS: GP71209831

S/n	Qty	Items	U/price	Amount
1	2	Rear Fender Top Inner Trimboard <i>crushed</i>	\$285.41	\$570.82 ✓
2	1	Rear R/H Fender Air Duct <i>Replaced</i>		\$84.60 ✗
3	1	Terminal Battery Fuse <i>new</i>		\$135.60 ✗
4	1	Rear Exhaust Aluminium Cover <i>crushed</i>		\$103.60 ✓
5)	2	Rear Bumper Side Spooge @ 89.50	179. ✓	
			Total:-	\$894.62
6)	1	Tail Cover <i>Debond</i> <i>crushed</i>	122.40 ✓	
7)	2	Spare Tyre Panel Side Board @ 95.70 <i>RH Debond</i>	191.40 95.70	1366.92
8)	1	Spare Tyre Side Panel RH <i>Distorted</i>	295.40 ✓	1093.53