

Not Authorized
Respray B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

AAD2008-031

81093-30

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

07 AUG 2020

SHD 5986G

JTDKB3FU403075667

TOYOTA

PRIUS

5.8.2020

TOKIO MARINE

1/11/2018

PART	LIST	
1 REAR BUMPER	\$ R	442.60 X
1 REAR BUMPER REINFORCEMENT	\$ B	332.70 ✓
1 REAR BUMPER TOWING COVER	\$ R	15.40 ✓
1 GUARD, REAR BUMPER, CENTER	\$ R/LH	576.30 ✓
1 REAR BUMPER SIDE RETAINER LH	\$ S	116.50
1 REAR BUMPER SIDE RETAINER RH	\$ S	117.70
1 REAR TAILGATE	\$ R	1,147.80
1 REAR TAILGATE OUTER GARNISH	\$ S	925.60
1 REAR TAILGATE WEATHERSTRIP	\$ S	372.30
1 PANEL SUB-ASSY, BODY LOWER BACK	\$ S	650.30
1 TAILLAMP LOWER RH	\$ S	502.00
1 TAILLAMP UPPER RH	\$ S	451.80
1 REAR BUMPER SIDE RH	\$ S	123.70
1 REAR BUMPER SIDE LH	\$ S	123.70
1 TAILLAMP LOWER LH	\$ S	502.00
1 TAILLAMP UPPER LH	\$ S	443.30
1 COVER, DECK TRIM, REAR	\$ S	126.70
1 COVER, FLOOR UNDER, NO.1	\$ S	175.10
1 COVER, FLOOR UNDER, NO.2	\$ S	241.90
1 COVER, REAR FLOOR	\$ S	229.90
1 REAR COMBINATION LAMP COVER	\$ S	64.50
TOTAL	\$	7,681.80
25%	\$	1,920.45
	\$	5,761.35

Special Nett

Trans-cab Auto Services Pte Ltd

AAD2008-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

UO./GST Reg. No. 201019626G

HD 5986G

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	75.00	X
1 REAR TAILGATE TOYOTA LOGO	\$	47.00	X
1 REAR TAILGATE WORDING 'PRIUS'	\$	52.90	X
1 REAR TAILGATE WORDING 'HYBRID'	\$	53.50	X
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	80.00	X
1 REAR TAILGATE STICKER '6555-3333'	\$	80.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	305.00
1 REAR WHEEL RIM	\$	1,879.40	
1 REAR TYRE 195/65/15	\$	350.00	
1 REAR RH BUMPER RETAINER CLIP	\$	65.00	
1 REAR LH BUMPER RETAINER CLIP	\$	65.00	
1SET TAILLAMP LOWER CLIP	\$	40.00	
1SET TAILLAMP UPPER CLIP	\$	40.00	
1 Rear Licence Plate with Moulding	\$	130.00	
1 REAR END PANEL INNER TRIM CLIP	\$	55.00	
TOTAL	\$	3,892.80	

TOTAL PARTS \$ 9,654.15**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,000.00	2201

AAD2008-031

ns-cab Auto Services Pte Ltd

2 Ang Mo Kio Street 63 Singapore 569111

No. : 6287 6666 Fax No. : 6257 1330

/GST Reg. No. 201019626G

D 5986G

To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,000.00	1501
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
TOTAL	\$	5,650.00	

Over All Total \$ **15,304.15**

(PART-BY-PART) Repair Days

20 Days

1 1/2 days

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: