

Date: 08.08.2020
Vehicle No: SLV1533P
Model: TOYOTA CHR HYBRID
Chassis: ZYX102075097-2017
Reg. Year: 2017

Third Party Insurer: INDIA
Third Party Veh No: SHA7824T
Date of Accident: 01.08.2020

*Not Authorized
Running B4 paint
3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		<i>Bu</i> \$878.60
2	REAR BUMPER CLIPS	8	\$5.50	<i>m</i> \$44.00
3	REAR BUMPER LOWER LIP COVER	1	387.00	<i>cm</i> \$496.80
4	REAR TAILGATE	1		REPAIR
5	REAR END PANEL	1		REPAIR
SUB TOTAL				\$1,419.40
LESS 25%				-\$354.85
PARTS TOTAL				\$1,064.55

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00 *300*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR TAILGATE, REAR END PANEL & ETC.

\$700.00 *640*

LABOUR CHARGES TO REMOVE & REFIX REAR BUMPER REVERSE SENSOR & ETC. TO EFFECT REPLACE OF REAR BUMPER.

\$100.00 *50*

TO CHECK WIRING & ELECTRICAL WIRING SYSTEM.

\$80.00 *15*

LABOUR TOTAL \$1,380.00

TingAn TOTAL \$2,444.55

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office
6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch
551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

