

# TTS EUROCARS PTE LTD

383 Sin Ming drive Singapore 575717

Date : 07.08.2020

## RE: VEHICLE REPAIR QUOTATION

Insurance Company	:	AIG Asia Pacific Insurance P/L
Vehicle Reg No	:	<b>SLZ1986U</b>
Name of Insured	:	
Policy Number	:	
Date of Accident	:	07.08.2020
Tyre of Claim	:	Third Party Claim
Model	:	BMW 523I 2.5AT
Chassis No	:	WBAFP32060C865362

We are please to submit our estimate of repairs to the above mention vehicle.

		Parts	Labour
1	FRONT BUMPER	\$ 1,626.44	
2	TOW HOOK COVER	\$ 154.64	
3	REINFORCEMENT UPPER	\$ 795.93	
4	SPONGE	\$ 85.16	
5	FRONT BUMPER LOWER GRILLE	\$ 99.56	
6	FRONT BUMPER FOG LAMP	\$ 329.46	
7	FRONT HEADLAMP RH	\$ 2,585.78	
8	FRONT BUMPER GRILLE RH	\$ 189.66	
9	FRONT BUMPER GRILLE LH	\$ 189.66	
10	FRONT BUMPER LOGO	\$ 139.63	
		<b>Sub Total Parts</b>	
		<b>\$ 6,195.92</b>	
		<b>Less 5%</b>	
		<b>\$ 309.80</b>	
		<b>Total Parts</b>	
		<b>\$ 5,886.12</b>	
1	Sundries	\$	50.00
2	Wiring connection and check.	\$	150.00
3	Tuff kote and spray anti rust proofing	\$	150.00
4	Labour charges to dismantle & refix front bumper front fog lamp cover, side retainer, chrome lower To repair and adjust affected portion to specific dimension.	\$	500.00
5	To spray paint front bumper, front Rh fender and all other accident affected portion	\$	500.00
6	Remove and replace front bumper sensor	\$	150.00
7	To supply and install front bumper plate with holder	\$	55.00
7	To conduct ECU programming, check and clear fault codes, restore programme modules	\$	350.00
Total (Labour)		<b>\$</b>	<b>1,905.00</b>

Sub Total :	\$5,886.12 + \$1,905.00	\$	7,791.12
GST 7%		\$	545.38
<b>Grand Total :</b>		<b>\$</b>	<b><u>8,336.50</u></b>

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval.