



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

DA/FC(SHC8598D)
DOA: 03/08/2020@1730

MS FIRST CAPITAL INSURANCE LTD
ATTN: THE MOTOR CLAIMS DEPT

07-08-20

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SLU 7316 R - TOYOTA WISH 1.8X CVT ABS D/AIRBAG
CHASSIS NO: ZGE206039453 (12/2017)

1 pc	Front headlamp LH <i>scr</i> ✓	\$ 950.00
1 pc	Front bumper <i>horn</i> ✓	\$ 584.00
1 pc	Front bumper retainer LH <i>new</i> ✓	\$ 60.00
1 pc	Front bumper foglight LH ?	\$ 355.00
1 pc	Front bumper foglight cover LH <i>mls</i> ✓	\$ 96.00
1 pc	Front bumper grille LH <i>cm</i> ✓	\$ 48.00
1 pc	Front bumper reinforcement <i>lt</i> ✓	\$ 285.00
1 pc	Front bumper sponge <i>cm</i> ✓	\$ 100.00
		\$ 2,478.00
	LESS 25%	\$ 619.50
		\$ 1,858.50

Check wiring function

\$ ~~40.00~~ 30

Remove necessary parts: jacking, panel beating, repair and
straighten front inner panel, front bonnet, front fender LH
inclusive replacing the above.

\$ ~~480.00~~ 300

Putty and respray front inner panel, front bonnet, front
fender LH and front bumper (PEARL COL)

\$ ~~600.00~~ 450 500

ADD 7% GST

\$ 2,978.50

\$ 208.50

\$ 3,187.00

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.
All parts are subject to availability.

CHARN'S CUSTOMCRAFT

IF other parts requested *Supp*
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Up 90010068
3 days
L/S
17/08/2020
P1425
Resy after
repair

front no plate (S/N) 35 X