



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 6271 7054, 6273 3304 FAX: 6273 6676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M GST Reg. No. M90367863L

DA/FC(SHC8598D)

DOA: 03/08/2020@1730

MS FIRST CAPITAL INSURANCE LTD

07-08-20

ATTN: THE MOTOR CLAIMS DEPT

OD CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SLU 7316 R - TOYOTA WISH 1.8X CVT ABS D/AIRBAG

CHASSIS NO: ZGE206039453 (12/2017)

1 pc	Front headlamp LH	\$	950.00
1 pc	Front bumper	\$	584.00
1 pc	Front bumper retainer LH	\$	60.00
1 pc	Front bumper foglight LH	\$	355.00
1 pc	Front bumper foglight cover LH	\$	96.00
1 pc	Front bumper grille LH	\$	48.00
1 pc	Front bumper reinforcement	\$	285.00
1 pc	Front bumper sponge	\$	100.00
		\$	2,478.00
	LESS 25%	\$	619.50
		\$	1,858.50
	Check wiring function	\$	40.00
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front bonnet, front fender LH inclusive replacing the above.	\$	480.00
	Putty and respray front inner panel, front bonnet, front fender LH and front bumper (PEARL COL)	\$	600.00
		\$	2,978.50
	ADD 7% GST	\$	208.50
		\$	3,187.00

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....